Adjuster Report 11/21/22, 9:42 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002861/KPA3Q2

21/11/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700042717 **Claimant Vehicle**

SLZ5160J Insured Vehicle No: SCA65Y No:

01/03/2021 Nature of Claim: TP Claim No: 5198430524SG Date of Loss:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ5160J**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6552003 Reg. Date: 07/05/2018 (Man. Year: 2018) Chassis No: GP71209856 Colour: Metallic Pearl White Odometer: 191814 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15 Front Left Side: Rear Left Side: Triangle 3 mm Triangle 4 mm Triangle 3 mm Rear Right Side: Triangle 4 mm Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,023.74	1,191.60	3,832.14	76.28
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,370.00	1,115.00	1,255.00	52.95
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,393.74	2,306.60	5,087.14	68.80
Ар	proved Total (Overridden) (S\$)		1,850.00		
	Nett Amount (S\$)	7,393.74	1,850.00	5,543.74	74.98
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 03/03/2021

A T Auto Consultant (HQ)

04/03/2021 B/113 Teck Whye Lane, #05-650 Date Inspected: Inspected At:

Singapore 680113

Estimated Period of Repair: 4.0 days

Adjuster: **KENNETH KONG** Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part N	o. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Repair	1,293.33 FL	*- FL
2	1	*TAILGATE LOCK	Repair	186.30 FL	*- FL
3	1	*TAILGATE WINDSCREEN MOULDING	Not Necessary	85.00 FL	*- FL
4	1	*TAILGATE CHROME MOULDING	Serviceable	393.30 FL	*- FL
5	1	*TAILGATE WEATHER STRIP	Serviceable	286.00 FL	*- FL
6	1	*TAILGATE EMBLEM HONDA	Necessary	86.00 FL	*86.00 FL
7	1	*TAILGATE EMBLEM SHUTTLE	Necessary	85.00 FL	*85.00 FL
8	1	*TAILGATE EMBLEM HYBRID	Necessary	56.00 FL	*56.00 FL
9	1	*REAR BUMPER	Buckled / Dented	1,225.00 FL	*950.00 FL
10	2	*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	96.00 FL	*- FL
11	2	*REAR BUMPER REFLECTOR LH/RH	Serviceable	98.00 FL	*- FL
12	1	*REAR END PANEL	Repair	588.00 FL	*- FL
13	1	*REAR END PANEL TOP GARNISH	Serviceable	198.00 FL	*- FL
14	1	*REMOTE KEY BUZZER	Serviceable	88.00 FL	*- FL
15	1	*REMOTE KEY BUZZER BRACKET	Repair	18.00 FL	*- FL
16	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
17	1	*SET REVERSE SENSOR	Shorted	320.00 FS	*200.00 FS
18	1	*SET REVERSE CAMERA	Serviceable	350.00 FS	*- FS
F=Fra	inchise part. S=S	pcNett. L=ListItemDisc.	_		
			Sub Total (S\$)	5,501.93	1,427.00
		- List Item Discount	on L Items 10.00/20.00% (S\$)	478.19	235.40
			Total Parts (S\$)	5,023.74	1,191.60
		Report was unsubmitted d	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PART	S New	800.00	400.00
SPRAY PAINTING ON ACCIDENT AREAS	New	800.00	600.00
WIRING CHARGES	New	100.00	15.00
REMOVE/REFIX REVERSE SENSOR	New	100.00	50.00
REMOVE/REFIX REVERSE CAMERA	New	100.00	50.00
TRANSFER TAILGATE GLASS	New	200.00	0.00
TRANSFER TAILGATE COMPONENT	New	150.00	0.00
APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (S		2,370.00	1,115.00
	DUIT Items PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PART SPRAY PAINTING ON ACCIDENT AREAS WIRING CHARGES REMOVE/REFIX REVERSE SENSOR REMOVE/REFIX REVERSE CAMERA TRANSFER TAILGATE GLASS TRANSFER TAILGATE COMPONENT APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS New SPRAY PAINTING ON ACCIDENT AREAS New WIRING CHARGES New REMOVE/REFIX REVERSE SENSOR New TRANSFER TAILGATE GLASS New TRANSFER TAILGATE COMPONENT New	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS SPRAY PAINTING ON ACCIDENT AREAS WIRING CHARGES REMOVE/REFIX REVERSE SENSOR New 100.00 REMOVE/REFIX REVERSE CAMERA New 100.00 TRANSFER TAILGATE GLASS New 150.00 APPLY UNDERCOATING TO ABOVE AFFECTED AREAS New 120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >