



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 3321S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	548.50	-
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	79.60	-
1	FRONT FENDER LH	DISTORTED	647.40	647.40
1	FRONT FENDER COWLING LH	TORN	156.70	156.70
1	SIDE MIRROR ASSY	DAMAGED	758.90	758.90
1	SIDE MIRROR SIGNAL LAMP LH	CRACKED	137.30	137.30
1	SIDE MIRROR BACK COVER	TO REPAIR SEE LABOUR	76.30	-
1	FRONT DOOR LH	DISTORTED	1,298.50	1,298.50
2	FRONT DOOR HINGES LH @\$69.80	BENT (1 PC ONLY)	139.60	69.80
1	FRONT DOOR CHECKER LH	NOT NECESSARY	68.90	-
1	FRONT DOOR LOCK LH	NOT NECESSARY	184.00	-
1	FRONT DOOR LATCH LH	NOT NECESSARY	80.60	-
1	FRONT DOOR STOPPERS	NOT NECESSARY	33.70	-
2	FRONT DOOR STICKERS LH @\$28.60	NECESSARY	57.20	57.20
1	FRONT DOOR OUTER HANDLE LH	NOT NECESSARY	145.60	-
1	FRONT DOOR OUTER HANDLE KNOB LH	NOT NECESSARY	34.50	-
1	FRONT DOOR OUTER MOULDING LH	NOT NECESSARY	67.40	-
1	FRONT DOOR WEATHERSTRIP LH	NOT NECESSARY	90.10	-
1	FRONT DOOR FRAME WEATHERSTRIP LH	NOT NECESSARY	87.80	-
1	FRONT DOOR TRIM BOARD LH	NOT NECESSARY	546.10	-
1	FRONT DOOR WINDOW REGULATOR	NOT NECESSARY	99.20	-
1	FRONT DOOR WINDOW REGULATOR MOTOR	NOT NECESSARY	406.90	-
1	FRONT DOOR WINDOW RUN CHANNEL LH	NOT NECESSARY	156.20	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	397.50	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	NOT NECESSARY	78.50	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	402.30	-
1	FRONT LOWER ARM LH	NOT NECESSARY	345.20	-
1	FRONT STABILIZER LINK LH	NOT NECESSARY	98.60	-
1	FRONT WHEEL BEARING W HUB LH	NOT NECESSARY	398.70	-

Report Ref No. CS/AGI21002862/Atd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RIM	NOT NECESSARY	203.30	-
	LESS 20% DISCOUNT		-1,565.02	-625.16
			6,260.08	2,500.64
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT FENDER COWLING CLIPS (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT/STRAIGHTEN/REALIGN ACCIDENT AFFECTED PORTION.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND SIDE MIRROR BACK COVER.		1,200.00	600.00
	TO RESPRAY ACCIDENT AFFECTED PORTION.		1,200.00	700.00
	TO TUFF COAT AFFECTED AREAS.		120.00	50.00
	TO CONDUCT WIRING CHECK AND REPAIR.		100.00	30.00
	TO CONDUCT WATER LEAK TEST.	NOT NECESSARY	100.00	-
	TO REMOVE/TRANSFER DOOR MECHANISM.		150.00	80.00
			2,870.00	1,460.00
<b>GRAND TOTAL</b>			<b>9,160.08</b>	<b>3,990.64</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/AGI21002862/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.