

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 362K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	DENTED / BENT	2,419.20	1,982.12
2	TAILGATE LOWER 'L' BRACKET @\$118.00 (CONSISTENT)	N/S BENT	236.00	118.00
2	TAILGATE LOWER 'L' BRACKET RUBBERS @\$95.00 (CONSISTENT)	N/S CUT	190.00	95.00
2	TAILLAMPS @\$250.00 (CONSISTENT)	CRACKED	500.00	330.00
1	REAR LICENCE PLATE LAMP (CONSISTENT)	CRACKED	145.00	118.00
1	REAR LICENCE PLATE BRACKET (CONSISTENT)	BENT	229.00	164.00
1	DROPSIDE GATE LOWER MEMBER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	899.00	-
1	TAILGATE LOCK LATCH N/S (CONSISTENT)	TO REPAIR SEE LABOUR	285.00	-
1	REAR EXHAUST (CONSISTENT)	BENT	820.00	655.62
1	REAR EXHAUST MOUNTING (CONSISTENT)	NOT NECESSARY	50.00	-
1	FRONT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,455.00	-
1	FRONT PANEL 'FUSO' EMBLEM (CONSISTENT)	NECESSARY	185.00	154.12
1	FRONT GRILLE (CONSISTENT)	CRACKED	680.00	615.00
1	FRONT GRILLE LOGO (CONSISTENT)	NECESSARY	68.00	66.00
1	FRONT BUMPER (CONSISTENT)	BENT	1,210.00	795.48
2	FRONT BUMPER SIDE PROTECTORS @\$650.00 (CONSISTENT)	DEFORMED / TORN	1,300.00	682.00
2	FRONT BUMPER BRACKETS @\$185.00 (CONSISTENT)	BENT	370.00	210.00
1	FRONT BUMPER CROSS MEMBER (CONSISTENT)	TO REPAIR SEE LABOUR	680.00	-
2	HEADLAMPS @\$1200.00 (CONSISTENT)	CRACKED	2,400.00	1,250.02
2	FRONT SIGNAL LAMPS @\$305.00 (CONSISTENT)	CRACKED	610.00	490.00
1	FRONT CABIN REAR PILLAR N/S (CONSISTENT)	TO REPAIR SEE LABOUR	820.00	-
1	AIR CON BLOWER (CONSISTENT)	NOT NECESSARY	1,850.00	-
1	AIR CON HEATER ASSY (CONSISTENT)	NOT NECESSARY	2,880.20	-
	LESS 25% DISCOUNT		-	-1,931.34
			20,281.40	5,794.02

Report Ref No. CC4/ASM21002873/Uga3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET TAILGATE 70KM/H & 13 PAX STICKER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET TAILGATE CORPORATE STICKER (SN) (CONSISTENT)	NECESSARY	380.00	300.00
1	TAILGATE INNER ALUMINIUM PLATE (SN) (CONSISTENT)	SERVICEABLE	800.00	-
1	SET TAILGATE INNER ALUMINIUM PLATE RIVET (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET REAR REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	REAR LICENCE PLATE (SN) (CONSISTENT)	BENT	50.00	14.00
2	REAR CHASSIS TOP FRAMES @\$1500.00 (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	3,000.00	-
1	REAR CARGO DECK STEP BRACKET (SN) (CONSISTENT)	BENT	180.00	120.00
1	FRONT LICENCE PLATE (SN) (CONSISTENT)	BENT	20.00	14.00
1	SET FRONT 'S' POWER STICKER (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	SET FRONT GRILLE CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			4,910.00	738.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACED REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REPLACE REAR EXHAUST .		100.00	60.00
	TO DISMANTLE & REFIX REAR CARGO DECK FOR REPAIR CHASSIS .		680.00	380.00
	TO SPRAY RUST PROOFING .		180.00	60.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF DROPSIDE GATE LOWER MEMBER N/S,TAILGATE LOCK LATCH N/S,FRONT PANEL,FRONT BUMPER CROSS MEMBER ,FRONT CABIN REAR PILLAR N/S AND REAR CHASSIS TOP FRAMES.		2,800.00	1,300.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,600.00
			6,540.00	3,480.00
	GRAND TOTAL		31,731.40	10,012.02



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		8,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21002873/Uga3q2

CHUA KANG SENG
Licensed Appraiser