

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002878/AVF3E2

Date: 04/06/2021

REFERENCE

Insured/Claimant:	PANG CHING HOO	Policy No:	1900083224		
Date of Loss:	25/02/2021	Nature of Claim:	OD	Claim No:	4359025409SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EA2318G		
Make & Model:	AUDI A4, 1.4 (A)	Engine No:	CVK077194
Reg. Date:	30/03/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF49KA042978
Colour:	Grey	Odometer:	41375 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,223.00	8,751.44	7,471.56	46.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,402.00	3,022.00	2,380.00	44.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,625.00	11,773.44	9,851.56	45.56
+ GST 7.00/7.00% (S\$)	1,513.75	824.14	689.61	45.56
Nett Amount (S\$)	23,138.75	12,597.58	10,541.17	45.56

INSPECTION

Date of Assignment:	03/03/2021		
Date Inspected:	03/03/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP (21PCS)	Damaged	36.00 FS	*28.16 FS
4	1		*FRONT BUMPER CLOSING ELEMENT LOWER CTR	Not Necessary	210.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE RH	Deformed	63.00 FS	*50.08 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Not Necessary	365.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION RH	Damaged	38.00 FS	*29.84 FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
10	1		*FRONT BUMPER COVER	Not Necessary	127.00 FS	*- FS
11	1		*CAUTION STICKER LABEL	Not Necessary	14.00 FS	*- FS
12	1		*AIRCON STICKER LABEL	Not Necessary	8.00 FS	*- FS
13	1		*FROONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT BRACKET LH / RH	Not Necessary	58.00 FS	*- FS
15	1		*LOW TONE FANFARE RH	Not Necessary	126.00 FS	*- FS
16	1		*SPRING SHACKLE RH	Not Necessary	29.00 FS	*- FS
17	2		*FRONT PARKING AID SENSOR INNER / OUTER	Not Necessary	244.00 FS	*- FS
18	4		*FRONT PARKING SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
19	1		*FRONT FENDER RH	Dented	767.00 FS	*613.20 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
21	1		*FRONT FENDER END PLATE RH	Damaged	72.00 FS	*57.52 FS
22	1		*FRONT FENDER BRACKET RH	Not Necessary	35.00 FS	*- FS
23	1		*FRONT FENDER CENTRE BRACKET RH	Not Necessary	49.00 FS	*- FS
24	6		*FRONT FENDER POP RIVET	Not Necessary	20.00 FS	*- FS
25	1		*FRONT FENDER BRACKET RH	Not Necessary	32.00 FS	*- FS
26	1		*FRONT FENDER BRACE RH	Bent	118.00 FS	*94.40 FS
27	1		*FRONT FENDER WHEEL HOUSING LINER RH	Cracked	241.00 FS	*192.80 FS
28	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	233.00 FS	*- FS
29	1		*FRONT WHEEL SPOILER RH	Torn	73.00 FS	*58.40 FS
30	1		*FRONT WHEEL SPOILER TRIM RH	Not Necessary	36.00 FS	*- FS
31	1		*FRONT FENDER STONE CHIP GUARD	Not Necessary	51.00 FS	*- FS
32	1		*FRONT FENDER LEDGE COVER RH LONG	Not Necessary	31.00 FS	*- FS
33	1		*FRONT FENDER LEDGE COVER RH SHORT	Damaged	23.00 FS	*17.92 FS
34	1		*LED HEADLIGHT RH	Cut	7,693.00 FS	*6,154.40 FS
35	1		*HEADLIGHT LIFT CYLINDER RH	Not Necessary	210.00 FS	*- FS
36	1		*HEADLIGHT WASHER HOSE	Not Necessary	93.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE RH BIG	Not Necessary	28.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE RH SMALL	Not Necessary	12.00 FS	*- FS
39	1		*ALUMINIUM RIM RH FRONT	Not Necessary	1,142.00 FS	*- FS
40	1		*SUNDRIES	Necessary	250.00 FS	*25.12 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 16,223.00 8,751.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,402.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >