

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002879/AVF3E2

Date: 03/08/2021

REFERENCE

Insured/Claimant:	WUU SOK LAN	Policy No:	2100449313		
Date of Loss:	27/02/2021	Nature of Claim:	OD	Claim No:	2585268611SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDB9998D	Engine No:	CVN001833
Make & Model:	AUDI A4, 1.4 (A)	Chassis No:	WAUZZZF46GA012893
Reg. Date:	18/02/2016 (Man. Year: 2015)	Odometer:	58221 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,097.00	3,778.64	8,318.36	68.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,494.00	3,942.00	13,552.00	77.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,591.00	7,720.64	21,870.36	73.91
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	29,291.00	7,420.64	21,870.36	74.67
+ GST 7.00/7.00% (S\$)	2,050.37	519.44	1,530.93	74.67
Nett Amount (S\$)	31,341.37	7,940.08	23,401.29	74.67

INSPECTION

Date of Assignment:	03/03/2021		
Date Inspected:	03/03/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR A-PILLAR FRAME LH	Repair	2,675.00 FS	*- FS
2	1		*FRONT FENDER LH	Distorted	767.00 FS	*613.20 FS
3	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
4	1		*FRONT FENDER BRACE	Not Necessary	118.00 FS	*- FS
5	1		*FRONT FENDER CLOSING ELEMENT LH	Cracked	33.00 FS	*26.16 FS
6	1		*FRONT FENDER UPPER BRACKET	Not Necessary	34.00 FS	*- FS
7	1		*FRONT FENDER WHEEL HOUSING LINER LH	Deformed	240.00 FS	*191.60 FS
8	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	233.00 FS	*- FS
9	1		*FRONT FENDER LEDGE COVER LONG LH	Cracked	31.00 FS	*24.64 FS
10	1		*FRONT FENDER LEDGE COVER LH SHORT	Cracked	23.00 FS	*17.92 FS
11	1		*FRONT FENDER STONE CHIP GUARD LH	Cracked	51.00 FS	*40.32 FS
12	1		*FRONT DOOR SCUFF PLATE LH	Not Necessary	120.00 FS	*- FS
13	1		*FRONT DOOR LH	Dented	3,192.00 FS	*2,553.60 FS
14	1		*FRONT DOOR OUTER DOOR SEAL LH	Necessary	205.00 FS	*164.00 FS
15	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
16	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
17	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
18	1		*FRONT DOOR ATTACHMENT PARTS LH	Not Necessary	1,050.00 FS	*- FS
19	1		*FRONT DOOR CATCH LH	Damaged	105.00 FS	*84.00 FS
20	1		*FRONT DOOR INNER SEAL LH	Not Necessary	205.00 FS	*- FS
21	1		*FRONT DOOR UPPER HINGE LH	Not Necessary	44.00 FS	*- FS
22	1		*FRONT DOOR UPPER HINGE VALVES LH	Not Necessary	46.00 FS	*- FS
23	2		*FRONT DOOR LOWER HINGE VALVES LH	Not Necessary	90.00 FS	*- FS
24	1		*EXTERIOR MIRROR MOUNTING LH	Not Necessary	1,089.00 FS	*- FS
25	1		*MIRROR CAP	Not Necessary	289.00 FS	*- FS
26	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
27	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
28	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
29	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
30	1		*SUNDRIES	Necessary	350.00 FS	*63.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,097.00 3,778.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	0.00
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
4	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	350.00
5	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO CUT OUT LHS A-PILLAR AND HS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	1,750.00
6	TO RESPRAY LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HINGES, LHS A-PILLAR, LHS SILL PANEL AND DOOR ENTRANCES	New	5,100.00	1,650.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			17,494.00	3,942.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >