



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:Kian Chuan			Ref: CC4/ASM21002881/Kgs3q2 Date: 28/04/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 7133L	Veh. Inspected	EC 3000E	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M0329M	Excess (\$)	0.00	
Assign From		Assign Date	03/03/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GK81200017	Colour	METALLIC DARK BLUE	
Odometer	37985 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	8 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	8 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	8 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/02/2021	Inspection Date	04/03/2021	
Survey held at	HENDERSON MOTORS BLK 21 SIN MING IND EST #01-54 SINGAPORE 575679			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	