

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21002882/T1QD3E2

**Date:** 07/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBF3775Y

**Insured Vehicle No :** SGT7840H

Date of Loss: 25/02/2021

Nature of Claim: TP

Claim No: 2908614593SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF3775Y**

Make & Model: TOYOTA HIACE, 2.5 (A)

Engine No: 1KD2625650

Reg. Date: 30/09/2016 (Man. Year: 2016)

Chassis No: KDH2010199476

Colour: White

Odometer: 162571 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 08/03/2021

Estimated Period of Repair: 10.0 days

Inspected At:

Jl Auto Services Pte Ltd (HQ)  
Blk 3006 UBI ROAD 1 #01-346  
Singapore 408700

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REVERSE SENSOR	Necessary	0.00 F	*- F
5	1		*TAILGATE	Bent	0.00 F	*- F
6	1		*TAILGATE LOCK	Bent	0.00 F	*- F
7	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
8	1		*TAILGATE GARNISH	Deformed	0.00 F	*- F
9	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE 5PAX STICKER	Necessary	0.00 F	*- F
11	1		*TAILGATE 70KM/H STICKER	Necessary	0.00 F	*- F
12	1		*TAILGATE WINDSCREEN SEALANT	Necessary	0.00 F	*- F
13	1		*TAILGATE WINDSCREEN MOULDING	Necessary	0.00 F	*- F
14	2		*REAR TAILLAMP LH & RH	Cracked	0.00 F	*- F
15	1		*REAR STEP PANEL	Bent	0.00 F	*- F
16	1		*REAR END PANEL	Bent	0.00 F	*- F
17	1		*REAR END PANEL TOP GARNISH	Bent	0.00 F	*- F
18	1		*TAILLAMP APRON PANEL RH	Deformed	0.00 F	*- F
19	1		*SPARE TYRE PANEL SCREW	Bent	0.00 F	*- F
20	1		*SPARE TYRE PANEL CARRIER	* Check	0.00 F	*- F
21	1		*TAILGATE WEATHERSTRIP	Cut	0.00 F	*- F
22	1		*REAR FLOOR PANEL	Repair	0.00 F	*- F
23	1		*REAR EXHAUST	Repair	0.00 F	*- F
24	1		*FRT BUMPER	Deformed	0.00 F	*- F
25	1		*FRT BUMPER SIDE RETAINER RH	Cracked	0.00 F	*- F
26	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
27	1		*FRT RH HEADLAMP	Cut	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$)</b>	<b>0.00</b>	<b>0.00</b>
-------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**