



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 619P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	487.90	487.90
1	FRONT BUMPER GRILLE	NOT NECESSARY	77.50	-
1	FRONT BUMPER REINFORCEMENT	DENTED	321.00	321.00
2	FRONT BUMPER SIDE RETAINER L/R @\$20.60	O/S DAMAGED	41.20	20.60
1	FRONT GRILLE	CRACKED	351.80	351.80
1	FRONT GRILLE BRACKET	CRACKED	76.00	76.00
1	FRONT GRILLE EMBLEM "H" LOGO	NECESSARY	23.40	23.40
1	FRONT GRILLE MOULDING	NOT NECESSARY	95.00	-
1	FRONT GRILLE OUTER COVER	CRACKED	421.00	421.00
2	FRONT HEADLAMP LOWER BRACKET L/R @\$35.00	O/S CRACKED	70.00	35.00
1	FRONT RH ARCH GARNISH	NOT NECESSARY	185.00	-
1	FRONT RH ARCH GUIDE GARNISH	NOT NECESSARY	31.60	-
1	FRONT RH HEADLAMP	CRACKED	1,784.50	1,784.50
	LESS 20% DISCOUNT		-	-704.24
			3,965.90	2,816.96
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	40.00	20.00
1	FRONT NUMBER PLATE (SN)	CUT	25.00	25.00
1	FRONT NUMBER PLATE HOLDER (SN)	CUT	50.00	30.00
			165.00	105.00
<u>LABOUR</u>				
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING (TO FR).		60.00	30.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		600.00	400.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		500.00	300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	50.00	-
			1,210.00	730.00
GRAND TOTAL			5,340.90	3,651.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/AGI21002886/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.