

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21002887/UPS3Q2
Date: 05/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100490795
Claimant Vehicle No :	SLX1660U	Insured Vehicle No :	SLH9013U
Date of Loss:	02/03/2021	Nature of Claim:	TP
		Claim No:	6300900319SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX1660U		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Engine No:	G4FGJU150502
Reg. Date:	20/03/2018 (Man. Year: 2018)	Chassis No:	KMHD841CMJU646468
Colour:	Silver	Odometer:	190546 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,569.20	3,284.16	7,285.04	68.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,740.00	1,390.00	44.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,699.20	5,024.16	8,675.04	63.33
Approved Total (Overridden) (S\$)		4,000.00		

(S\$)	13,699.20	4,000.00	9,699.20	70.80
+ GST 7.00/7.00% (S\$)	958.94	280.00	678.94	70.80
Nett Amount (S\$)	14,658.14	4,280.00	10,378.14	70.80
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,522.00		
Global Sum Settlement (S\$)		4,520.00		

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	1,280.20 F	*1,280.20 FL
2	1		*BOOTLID H LOGO	Necessary	48.50 F	*48.50 FL
3	1		*BOOTLID ELANTRA EMBLEM	Necessary	62.00 F	*48.00 FL
4	1		*BOOTLID S EMBLEM	Necessary	65.00 F	*42.00 FL
5	2		*BOOTLID REFLECTORS	Not Necessary	900.00 F	*- FL
6	1		*BOOTLID INNER LOCK	Not Necessary	215.00 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	288.00 F	*116.00 FL
8	1		*REAR BUMPER	Torn	788.50 F	*459.40 FL
9	1		*REAR BUMPER LOWER GARNISH	Deformed	452.00 F	*250.40 FL
10	1		*REAR BUMPER REFLECTORS	O/S Scratched	210.00 F	*65.00 FL
11	1		*REAR BUMPER SPONGE	Not fitted	188.00 F	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Dented	495.00 F	*345.40 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	330.00 F	*- FL
14	3		*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Not Necessary	75.00 F	*- FL
15	1		*TAILLAMPS	O/S Cracked	1,962.00 F	*542.20 FL
16	1		*REAR END PANEL	Dented	666.00 F	*454.60 FL
17	1		*REAR END PANEL TOP GARNISH	Twisted	215.00 F	*78.50 FL
18	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	499.00 F	*- FL
19	1		*REAR FLOOR PANEL	Not Necessary	1,450.00 F	*- FL
20	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
22	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,569.20	4,030.20
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	746.04
Total Parts (\$)	10,569.20	3,284.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	50.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	880.00
Gross Labour Cost (S\$)			3,130.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >