

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21002888/T1QF3E2

Date: 02/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SBS6786C **Insured Vehicle No :** SMP1801K
Date of Loss: 01/03/2021 Nature of Claim: TP Claim No: 1777985441SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6786C**
Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D AT TURBO ABS (A) Engine No: 902926C1033923
Reg. Date: 04/08/2014 (Man. Year: 2013) Chassis No: WEB62808323125417
Colour: Multi-colour Odometer: 447092 km
Engine Capacity: 6374 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,312.00	1,312.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	520.00	520.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,832.00	1,832.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	128.24	128.24	0.00	0.00
Nett Amount (S\$)	1,960.24	1,960.24	0.00	0.00

INSPECTION

Date of Assignment: 03/03/2021
Date Inspected: 04/03/2021 Inspected At: Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SEALING FRAME;LHS;ENT DR	Deformed	313.00 F	*313.00 F
2	1		*GLASS.NO 1,ENT DR	Cut	420.00 F	*420.00 F
3	1		*BUMPERETTE;FRT BUMPERETTE.N/S	Cracked	536.00 F	*536.00 F
4	1		*BLINKER LAMP;FRT LEFT	Cracked	43.00 F	*43.00 F
					Total Parts (S\$)	1,312.00
						1,312.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR COST	New	520.00	520.00
			Gross Labour Cost (\$)	520.00
				520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >