

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002895/BBA3Q2
Date: 17/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993662
Claimant Vehicle No :	SJR6918A	Insured Vehicle No :	SMJ8840H
Date of Loss:	02/03/2021	Nature of Claim:	TP
		Claim No:	1473994938SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR6918A		
Make & Model:	MITSUBISHI LANCER, 1.6 CVT SPORTS GLX (A)	Engine No:	4G18KC6715
Reg. Date:	08/07/2009 (Man. Year: 2009)	Chassis No:	JMYSTCS3A9U005640
Colour:	Silver	Odometer:	258700 km
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,616.21	4,982.90	4,633.31	48.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,580.00	2,270.00	58.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,466.21	6,562.90	6,903.31	51.26
Approved Total (Overridden) (S\$)		5,300.00		

(S\$)	13,466.21	5,300.00	8,166.21	60.64
+ GST 7.00/7.00% (S\$)	942.63	371.00	571.63	60.64
Nett Amount (S\$)	14,408.84	5,671.00	8,737.84	60.64
+ Loss of Use (11.0 x S\$70.00/day) (S\$)		770.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,448.45		
Global Sum Settlement (S\$)		6,400.00		

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	853.50 FL	*789.00 FL
2	1		*BONNET INSULATOR	No such part	285.30 FL	*- FL
3	1		*BONNET LOCK	Not Damaged	207.90 FL	*- FL
4	1		*BONNET LOCK STICKER	Not Damaged	74.60 FL	*- FL
5	2		*BONNET HINGE	Not Damaged	294.00 FL	*- FL
6	1		*FRONT BUMPER	Broken	985.60 FL	*882.70 FL
7	2		*FRONT BUMPER GRILLE	Broken	778.80 FL	*589.00 FL
8	1		*FRONT BUMPER GRILLE LOGO	Necessary	214.20 FL	*105.00 FL
9	1		*FRONT BUMPER BRACKET	No such part	215.00 FL	*- FL
10	2		*FRONT BUMPER SIDE RETAINER	Necessary	337.00 FL	*120.00 FL
11	1		*FRONT BUMPER BUMPER LOWER GRILLE	Broken	215.50 FL	*153.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	425.30 FL	*313.00 FL
13	1		*FRONT BUMPER FOG LAMP COVER	N/S Broken	285.20 FL	*116.30 FL
14	1		*FRONT BUMPER LOWER LIP	No such part	341.20 FL	*- FL
15	1		*FRONT LICENSE PLATE	Bent	155.30 FL	*40.00 FL
16	2		*HEADLAMP	Broken	1,310.60 FL	*1,310.60 FL
17	2		*HEADLAMP LOWER BRACKET	No such part	290.40 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Not Damaged	699.20 FL	*- FL
19	1		*RADIATOR	Not Damaged	875.90 FL	*- FL
20	1		*A/C CONDENSER	Bent	862.40 FL	*862.40 FL
21	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
22	1		*BONNET SEALANT	Necessary	100.00 FS	*40.00 FS
23	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*BONNET STICKER	Necessary	60.00 FS	*40.00 FS
25	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*FRONT BUMPER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
28	2		*FRONT BUMPER FOG LAMP COVER CLIPS	Not Necessary	100.00 FS	*- FS
29	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
31	1		*A/C FLUID	Necessary	80.00 FS	*40.00 FS
32	1		*FRONT NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,586.90	5,511.00
- List Item Discount on L Items 10.00/10.00% (\$)	970.69	528.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	9,616.21
						4,982.90
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BONNET COMPONENT	New	150.00	70.00
2	R&R RADIATOR	New	150.00	0.00
3	R&R A/C CONDENSER	New	150.00	80.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	100.00	30.00
6	PANEL BEATING	New	1,400.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			3,850.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >