



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FF 8989S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FORK TUBES ASSY	NOT NECESSARY	980.00	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	95.00	-
2	FRONT SIDE COVER	O/S CUT	580.00	290.00
1	SIDE LOWER COVER O/S	CUT	220.00	220.00
1	FRONT RIM SHAFT	NOT NECESSARY	75.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	220.00	-
1	TOW COWLING INNER PANEL	CUT	105.00	105.00
1	WINDSHIELD	CRACKED	280.00	280.00
1	SIDE MIRROR O/S	CUT	200.00	145.00
1	HANDLE-BAR	NOT NECESSARY	255.00	-
1	SET HAND GRIP	NOT NECESSARY	100.00	-
1	SET BRAKE LEVER	SCRATCHED	86.00	60.00
1	SET FRONT SIGNALS	SERVICEABLE	95.00	-
1	TOP FOOTSTEP PANEL	CUT	185.00	185.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	720.00	-
1	EXHAUST PROTECTOR	CUT	85.00	85.00
1	EXHAUST LINK-PIPE COVER	CUT	65.00	65.00
1	REAR TAILBOARD	CUT	300.00	260.00
	LESS 10% DISCOUNT		-464.60	-169.50
			4,181.40	1,525.50
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	FRT NECESSARY	28.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	40.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	76.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	REAR BOX (SN)	CUT	380.00	280.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
			824.00	290.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PROVIDE TOWING SERVICE (LOD).	NOT NECESSARY	50.00	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO RESPRAY PAINTING.		800.00	400.00
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT FENDER AND EXHAUST ASSY.		380.00	300.00
			1,310.00	700.00
	GRAND TOTAL		6,315.40	2,515.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CS/AGI21002899/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.