

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002900/QPS3Q2
Date: 14/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100446254
Claimant Vehicle No :	SMG9590M	Insured Vehicle No :	SKX9264P
Date of Loss:	26/02/2021	Nature of Claim:	TP
		Claim No:	2026939033SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9590M	Engine No:	LEB6722504
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31302497
Reg. Date:	07/01/2019 (Man. Year: 2018)	Odometer:	122761 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,316.24	5,501.84	10,814.40	66.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	2,090.00	2,150.00	50.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,556.24	7,591.84	12,964.40	63.07
Approved Total (Overridden) (S\$)		6,050.00		

(S\$)	20,556.24	6,050.00	14,506.24	70.57
+ GST 7.00/7.00% (S\$)	1,438.94	423.50	1,015.44	70.57
Nett Amount (S\$)	21,995.18	6,473.50	15,521.68	70.57
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,869.95		
Global Sum Settlement (S\$)		6,800.00		

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 04/03/2021

Estimated Period of Repair: 6.0 days

Inspected At:

My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
 60 Jalan Lam Huat, Carros Centre #05-21
 Singapore 737869

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crumpled	658.00 FL	*658.00 FL
2	1		*FRONT BUMPER LOWER	Cut	415.90 FL	*320.00 FL
3	2		*FRONT BUMPER SIDE RETAINER	Serviceable	204.00 FL	*- FL
4	1		*FRONT FENDER RH	Repair	645.00 FL	*- FL
5	1		*FRONT FENDER WHEEL ARCH RH	Scratched	398.20 FL	*220.00 FL
6	1		*FRONT FENDER TOP GARNISH RH	Serviceable	215.00 FL	*- FL
7	1		*FRONT FENDER EMBLEM HYBRID RH	Necessary	68.00 FL	*68.00 FL
8	1		*FRONT SIDE MIRROR RH	Serviceable	548.00 FL	*- FL
9	1		*FRONT SHOCK ABSORBER RH	Serviceable	456.00 FL	*- FL
10	1		*FRONT KNUCKLE ARM RH	Serviceable	398.00 FL	*- FL
11	1		*FRONT KNUCKLE ARM BEARING RH	Serviceable	215.00 FL	*- FL
12	1		*FRONT LOWER ARM RH	Serviceable	489.00 FL	*- FL
13	1		*FRONT DOOR RH	Crumpled	1,259.00 FL	*1,125.00 FL
14	1		*FRONT DOOR BLACK TAPE RH	Necessary	30.10 FL	*30.10 FL
15	1		*FRONT DOOR OUTER MOULDING RH	Necessary	145.20 FL	*145.20 FL
16	1		*FRONT DOOR SUB SEAL RH	Serviceable	115.80 FL	*- FL
17	1		*FRONT DOOR LOWER SEAL RH	Broken	51.90 FL	*51.90 FL
18	1		*FRONT DOOR CENTRE SEAL RH	Crumpled	69.20 FL	*69.20 FL
19	1		*FRONT DOOR UPPER HINGE RH	Serviceable	131.90 FL	*- FL
20	1		*FRONT DOOR LOWER HINGE RH	Serviceable	195.10 FL	*- FL
21	1		*FRONT DOOR CHECKER RH	Serviceable	58.00 FL	*- FL
22	1		*FRONT DOOR POWER WINDOW MOTOR RH	Serviceable	554.50 FL	*- FL
23	1		*FRONT DOOR REGULATOR RH	Bent	510.30 FL	*382.00 FL
24	1		*FRONT DOOR SPEAKER RH	Serviceable	215.00 FL	*- FL
25	1		*FRONT DOOR OUTER HANDLE RH	Crumpled	367.60 FL	*367.60 FL
26	1		*FRONT DOOR LOCK ASSY RH	Jammed	389.00 FL	*310.00 FL
27	1		*FRONT DOOR INNER TRIM BOARD RH	Crumpled	687.20 FL	*498.00 FL
28	1		*FRONT DOOR FRAME WEATHERSTRIP RH	Serviceable	281.20 FL	*- FL
29	1		*DOOR CENTRE PILLAR (OUTER)	Repair	1,214.00 FL	*- FL
30	1		*DOOR CENTRE PILLAR INNER GARNISH RH	Serviceable	258.00 FL	*- FL
31	1		*REAR DOOR RH	Crumpled	1,259.00 FL	*960.00 FL
32	1		*REAR DOOR BLACK TAPE RH	Necessary	30.10 FL	*30.10 FL
33	1		*REAR DOOR OUTER MOULDING RH	Necessary	145.20 FL	*145.20 FL
34	1		*REAR DOOR SUB SEAL RH	Serviceable	115.80 FL	*- FL
35	1		*REAR DOOR LOWER SEAL RH	Serviceable	51.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR DOOR CENTRE SEAL RH	Serviceable	69.20 FL	*- FL
37	1		*REAR DOOR UPPER HINGE RH	Serviceable	131.90 FL	*- FL
38	1		*REAR DOOR LOWER HINGES RH	Serviceable	195.10 FL	*- FL
39	1		*REAR DOOR CHECKER RH	Serviceable	58.00 FL	*- FL
40	1		*REAR DOOR POWER WINDOW MOTOR RH	Serviceable	554.50 FL	*- FL
41	1		*REAR DOOR REGULATOR RH	Serviceable	510.30 FL	*- FL
42	1		*REAR DOOR SPEAKER RH	Serviceable	215.00 FL	*- FL
43	1		*REAR DOOR OUTER HANDLE RH	Serviceable	367.60 FL	*- FL
44	1		*REAR DOOR LOCK ASSY RH	Serviceable	389.00 FL	*- FL
45	1		*REAR DOOR INNER TRIM BOARD RH	Serviceable	687.20 FL	*- FL
46	1		*REAR DOOR FRAME WEATHERSTRIP RH	Serviceable	281.20 FL	*- FL
47	1		*SIDE SKIRTING RH	Crumpled	1,258.00 FL	*627.00 FL
48	1		*REAR FENDER RH	Serviceable	698.00 FL	*- FL
49	1		*REAR FENDER WHEEL ARCH RH	Scratched	398.20 FL	*220.00 FL
50	1		*REAR BUMPER	Serviceable	687.00 FL	*- FL
51	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
52	1		*FRONT FENDER INNER COWLING CLIPS	Serviceable	50.00 FS	*- FS
53	1		*FRONT FENDER WHEEL ARCH CLIPS	Necessary	30.00 FS	*20.00 FS
54	1		*FRONT FENDER SEALANT LH	Serviceable	80.00 FS	*- FS
55	1		*FRONT BUMPER LOWER COVER CLIPS	Necessary	50.00 FS	*30.00 FS
56	1		*SET FRONT DOOR INNER TRIM CLIPS	Serviceable	50.00 FS	*- FS
57	1		*SET REAR DOOR INNER TRIM CLIP	Serviceable	50.00 FS	*- FS
58	1		*SET REAR WHEELARCH CLIP	Necessary	30.00 FS	*20.00 FS
59	1		*SET SIDE SKIRTING CLIPS	Necessary	50.00 FS	*20.00 FS
60	1		*FRONT WHEEL RIM	Cut	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,185.30	6,747.30
- List Item Discount on L Items 20.00/20.00% (\$)	3,869.06	1,245.46
Total Parts (\$)	16,316.24	5,501.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
3	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
4	REMOVE AND REFIT FRT & REAR DOOR GLASS	New	160.00	60.00
5	TO REMOVE AND REFIT FRT & REAR DOOR MECHANISM	New	200.00	120.00
6	REMOVE AND REFIR FRONT UNDERCARRIAGE	New	400.00	0.00
7	TO RESPRAY UNDERCOATING	New	200.00	40.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	40.00
9	CONDUCT FULL WHEEL ALIGNMENT (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			4,240.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >