



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBY 1937K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,039.00	-
1	FRONT BONNET GRILLE	TO REPAIR SEE LABOUR	380.00	-
1	FRONT BONNET MECHANISM LOCK	SERVICEABLE	68.00	-
1	FRONT RH HEADLAMP	CRACKED	762.00	762.00
1	FRONT RH HEADLAMP APRON PANEL	BENT	48.00	48.00
1	FRONT RH HEADLAMP SIDE GARNISH	CRACKED	68.00	68.00
1	FRONT RH SIDE SIGNAL LAMP	SERVICEABLE	102.00	-
1	FRONT BUMPER	CRACKED	1,105.00	1,105.00
1	FRONT BUMPER PROTECTOR	CRACKED	169.00	169.00
2	FRONT BUMPER SIDE BRACKET L/R	BENT	176.00	176.00
2	FRONT BUMPER TOP CHROME L/R	SERVICEABLE	378.00	-
1	FRONT BUMPER TOWING COVER	SERVICEABLE	60.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	832.00	-
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	SERVICEABLE	56.00	-
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	416.00	-
	LESS 10% DISCOUNT		-	-232.80
			5,659.00	2,095.20
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	FRONT BUMPER NUMBER PLATE GARNISH (SN)	SERVICEABLE	50.00	-
			105.00	30.00
<u>LABOUR</u>				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING.		120.00	30.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00

Report Ref No. CS1/LAW21002902/Gqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR AND RE-CONSTRUCT CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BONNET GRILLE AND FRONT RH FENDER.	NOT NECESSARY	1,200.00	200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	-
			2,440.00	630.00
GRAND TOTAL			8,204.00	2,755.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS1/LAW21002902/Gqd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.