

Your Ref: (V)TWK/DAQ/pkf/0555.20

Date: 25th March 2020

Our Ref: CS1/LAW21002902/Gqd3e2

M/s Tan Kok Quan Partnership

1 Wallich Street #07-02

Guoco Tower

Singapore 078881

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SBY 1937K

INSURED VEHICLE: GBC 2863Z

ACCIDENT DATE: 23/09/2017

We thank you for your instruction on 03/03/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBY 1937K from M/s Aeon Auto Consultants LLP.
- b) Survey report by Ajax Inspection Services Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles SBY 1937K and GBC 2863Z
- d) Colour damaged vehicle photographs of SBY 1937K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SBY 1937K
Make & Model	: Mercedes Benz 190 Auto
Chassis Number	: WDB2010232F715110
Year of Registration	: 1990
Engine Capacity	: 1997 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.