

## PRE-REPAIR SURVEY REPORT NTUC Income Insurance Co-operative Ltd 73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556 Attention: Mr Thio Tse Kiat 26/09/2017 Survey Date: 27/09/2017 TP Report Date: 23/09/2017 Assign Date: GA190126 Our Ref: AVS2017-12612/PN Accident Date: 23/09/2017 TP Policy No: Place of Survey: V-Tech Auto Service Your Ref: MT/0962847-001 1 Soon Lee Street #06-04/05/06/07 Pioneer Centre Claim Type: Third Party R Munggam S/O 627605 Claimant: Singapore Apasamy Description of Vehicle: Mercedes-Benz 190 Auto Veh. No: SBY1937K Make/Model: Sum Insured (S\$): Market Value 10292422016095 Colour: Black Engine No: WDB2010232F715110 Mkt Value (S\$): \$8,000.00 **Engine Capacity:** 1,797cc Chassis No: 27/04/1990 NA Excess (S\$): Odometer: 108907 Reg. Date: Condition of Vehicle: Serviceable Good Modification: No Steering: General: Good Serviceable Paint work: Handbrake: Serviceable Footbrake: Tyre Make: Bridgestone Front Right Side: 6mm Front Tyre Size: 195/65R15 Front Left Side: 6mm Rear Left Side: Rear Right Side: 6mm Rear Tyre Size: 195/65R15 6mm Description of Damage: The vehicle sustained damage on the rear portion. The front bumper were among the items affected. Remarks: Our recommended amount for the cost of contract lumpsum repair is \$\$1,980.00 with approximately three (3) working days to complete. However, the amount was not finalized with the repairer. All the stated damage are subject to consistency of the mentioned accident.

COMPLETED US FEB 2018

Adjuster:

Patrick Ng

Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



djustment of Repair Cost for Vehicle:		f Repair Cost for Vehicle:	SBY1937K	Our Ref: AVS2017-12612/	
No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendatio S\$
ist Ite	ms				
1	1	Front bonnet	Not necessary	57.0	-
2	1	Front bonnet grille	Not necessary		-
3	1	Front bonnet mechanism lock	Not necessary	68.00	-
4	1	Front RH headlamp	Not necessary	762.00	
5	1	Front RH headlamp apron panel	Damaged	48.00	48.00
6	1	Front RH headlamp side garnish	Damaged	68.00	68.00
7	1	Front RH side signal lamp	Not necessary	102.00	
8	1	Front bumper	Damaged	1,105.00	1,105.00
9	1	Front bumper protector	Damaged	169.00	169.00
10	2	Front bumper side bracket L/R	Cracked	176.00	176.00
11	2	Front bumper top chrome L/R	Not necessary	378.00	
12	1	Front bumper towing cover	Not necessary	60.00	122
13	1	Front bumper reinforcement	Repair	832.00	
14	2	Front bumper reinforcement bracket L/R	Not necessary	56.00	-
15	1	Front RH fender	Not necessary	19 <del>44</del>	
			Sub Total:	3,824.00	1,566.00
				3,824.00	1,566.00

1	1	Front bumper clips- set	Necessary	30.00	20.00
2	1	Front bumper number plate	Not necessary	25.00	
3	1	Front bumper number plate garnish	Not necessary	50.00	
			Sub Total:	105.00	20.00
			Total Parts Price:	3,929.00	1,586.00

abou	r Cost		
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	100.00	30.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800.00	400.00
3	To provide labour, workmanship to change the above damaged bodyparts, repair and re-construct consistent to the accident.	1,000.00	400.00
4	To apply anti- rust chemical on repaired and replaced panel.	100.00	60.00
	Sub Total:	2,000.00	890.00
	Grand Total:	5,929.00	2,476.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd