

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21002905/T1BS3Q2
Date: 07/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SHC6814T	Insured Vehicle No :	SLW3402R
Date of Loss:	03/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000950

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6814T	Engine No:	D4FDEH313379
Make & Model:	KIA OPTIMA, 1.7 D CRDi (A)	Chassis No:	KNAGM414MF5593815
Reg. Date:	14/07/2015 (Man. Year: 2014)	Odometer:	561692 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,276.40	50.00	2,226.40	97.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	600.00	600.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,476.40	650.00	2,826.40	81.30
+ GST 7.00/7.00% (S\$)	243.35	45.50	197.85	81.30

Nett Amount (\$)	3,719.75	695.50	3,024.25	81.30
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 10/03/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2021)
Parts:	143	KIA OPTIMA 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6814T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S HEAD LAMP	Not Necessary	1,028.00 FL	*- FL
2	1		*FRONT BUMPER	Repair	531.00 FL	*- FL
3	1		*FRONT BUMPER EMBLEM	Not Necessary	44.00 FL	*- FL
4	1		*FRONT BUMPER O/S SIDE RETAINER	Not Necessary	16.00 FL	*- FL
5	1		*FRONT O/S WHEEL COVER	Not Necessary	116.00 FL	*- FL
6	1		*FRONT BUMPER O/S PROTECTOR	Not Necessary	51.00 FL	*- FL
7	1		*FRONT BUMPER O/S FOG LAMP COVER	Not Necessary	66.00 FL	*- FL
8	1		*FRONT O/S FENDER	Repair	384.00 FL	*- FL
9	1		*FRONT O/S FENDER INNER SHIELD	Not Necessary	120.00 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
11	1		*FRONT O/S FENDER STICKER	Necessary	30.00 FS	*30.00 FS
12	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
13	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,512.00	50.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	235.60	0.00
Total Parts (\$\$)	2,276.40	50.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO ADJUST FRONT O/S HEAD LAMP	New	40.00	0.00
2	TO CHECK FRONT O/S WHEEL ALIGNMENT	New	80.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ,ETC	New	600.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER	New	400.00	400.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (\$)			1,200.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >