

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002906/DGA3Q2
Date: 27/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800054376-02
Claimant Vehicle No :	SKA8182U	Insured Vehicle No :	SLU9761A
Date of Loss:	03/03/2021	Nature of Claim:	TP
		Claim No:	1818317542SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA8182U		
Make & Model:	MERCEDES-BENZ C180, 1.8 (A)	Engine No:	27182030045304
Reg. Date:	30/04/2010 (Man. Year: 2010)	Chassis No:	WDD2040492A377795
Colour:	Black	Odometer:	175524 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,247.10	21,249.41	26,997.69	55.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,840.00	4,020.00	4,820.00	54.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,087.10	25,269.41	31,817.69	55.74
Approved Total (Overridden) (S\$)		20,000.00		

(S\$)	57,087.10	20,000.00	37,087.10	64.97
+ GST 7.00/7.00% (S\$)	3,996.10	1,400.00	2,596.10	64.97
Nett Amount (S\$)	61,083.20	21,400.00	39,683.20	64.97
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		130.00		
Nett Liability (S\$)		22,966.45		

INSPECTION

Date of Assignment: 03/03/2021

Date Inspected: 03/03/2021

Estimated Period of Repair: 12.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	2,127.00 FL	*1,735.00 FL
2	1		*BOOTLID LOGO	Necessary	74.00 FL	*74.00 FL
3	1		*BOOTLID CGI EMBLEM	Necessary	101.00 FL	*45.00 FL
4	1		*BOOTLID C180 EMBLEM	Necessary	85.00 FL	*85.00 FL
5	1		*BOOTLID C&C EMBLEM	Necessary	100.00 FL	*85.20 FL
6	1		*BOOTLID CENTER CHROME	Mtg Broken	436.00 FL	*365.00 FL
7	2		*BOOTLID NO. PLATE LAMP L+R	Not Necessary	196.00 FL	*- FL
8	1		*BOOTLID INNER TRIM	Deformed / Bent	563.00 FL	*385.90 FL
9	1		*BOOTLID WEATHERSTRIP	Deformed	399.00 FL	*197.50 FL
10	2		*BOOTLID HINGE L+R	Bent	348.00 FL	*348.00 FL
11	2		*BOOTLID HINGE GARNISH L+R	Serviceable	298.00 FL	*- FL
12	1		*BOOTLID LOCK	Damaged	349.00 FL	*349.00 FL
13	1		*BOOTLID SWITCH	Not Necessary	298.00 FL	*- FL
14	1		*REAR WINDSCREEN MOULDING	Necessary	349.00 FL	*168.50 FL
15	1		*REAR BUMPER	Buckled / Torn	1,797.00 FL	*1,312.00 FL
16	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	192.00 FL	*- FL
17	1		*REAR BUMPER CENTER CHROME	Broken	417.00 FL	*120.00 FL
18	2		*REAR BUMPER SIDE CHROME L+R	Broken / Necessary	508.00 FL	*230.00 FL
19	1		*REAR BUMPER CENTER BRACKET	Broken / Bent	330.00 FL	*330.00 FL
20	2		*REAR BUMPER SIDE BRACKET L+R	Broken	346.00 FL	*140.00 FL
21	1		*REAR BUMPER UNDER COVER CENTER	Not Necessary	410.00 FL	*- FL
22	2		*REAR BUMPER UNDER COVER SIDEK L+R	Not Necessary	478.00 FL	*- FL
23	1		*REAR REINFORCEMENT BAR	Buckled	1,506.00 FL	*615.00 FL
24	1		*REAR BUMPER TOW HOOK COVER	Dislodged	79.00 FL	*79.00 FL
25	2		*TAIL LAMP L+R	Broken	1,762.00 FL	*1,084.00 FL
26	2		*TAIL LAMP PANEL L+R	Dented	958.00 FL	*770.00 FL
27	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	368.00 FL	*- FL
28	2		*REAR FENDER L+R	Dented	5,588.00 FL	*4,482.40 FL
29	2		*REAR FENDER OUTER GARNISH L+R	Broken	602.00 FL	*300.00 FL
30	1		*REAR FENDER INNER PANEL LH	Repair	1,789.00 FL	*- FL
31	2		*REAR FENDER INNER TRIM L+R	Bent	1,892.00 FL	*1,240.00 FL
32	2		*REAR FENDER INNER SHIELD L+R	Not Necessary	364.00 FL	*- FL
33	1		*REAR FENDER AIR DUCT LH	Deformed / Broken	101.00 FL	*101.00 FL
34	1		*REAR WHEEL HOUSING LH	Repair	1,829.00 FL	*- FL
35	1		*REAR END PANEL	Buckled	1,558.00 FL	*1,084.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR END PANEL TOP GARNISH	Broken	463.00 FL	*197.00 FL
37	1		*SPARE WHEEL PANEL	Broken	2,421.00 FL	*449.00 FL
38	2		*SPARE WHEEL QUARTER PANEL L+R	Repair	1,552.00 FL	*- FL
39	1		*SPARE WHEEL PANEL TOP BOARD	Bent / Broken	569.00 FL	*355.32 FL
40	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	492.00 FL	*- FL
41	1		*REAR EXHAUST PIPE	Not Necessary	2,227.00 FL	*- FL
42	1		*REAR EXHAUST MUFFLER	Bent	980.00 FL	*980.00 FL
43	1		*REAR EXHAUST HEAT SHIELD	Cracked / Broken /Bent	226.00 FL	*184.30 FL
44	1		*REAR EXHAUST MOUNING	Not Necessary	101.00 FL	*- FL
45	1		*DRIVER SEAT BELT	Activated	1,680.00 FL	*650.00 FL
46	1		*FRONT PASSENGER SEAT BELT	Activated	1,671.00 FL	*650.00 FL
47	1		*DRIVER SEAT BELT BUCKLE	Serviceable	560.00 FL	*- FL
48	1		*FRONT PASSENGER SEAT BELT BUCKLE	Serviceable	560.00 FL	*- FL
49	2		*REAR SEAT BELT LH/RH	Activated	3,140.00 FL	*930.00 FL
50	2		*DRIVER HEAD REST AIR BAG	Damaged / Activated	1,829.00 FL	*788.00 FL
51	2		*FRONT PASSENGER HEAT REST AIR BAG	Damaged / Activated	1,789.00 FL	*788.00 FL
52	1		*SPARE WHEEL TOP BOARD INNER	Broken	380.00 FL	*380.00 FL
53	1		*SRS CONTROL MODULE	Activated	1,882.00 FL	*1,050.00 FL
54	1		*REAR NUMBER PLATE & CASING	Not Necessary	100.00 FS	*- FS
55	1		*SET REAR REVERSE SENSOR	Damaged	300.00 FS	*250.00 FS
56	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
57	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
58	1		*BOOTLID INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS
59	1		*BOOTLID CENTER CHROME CLIPS	Necessary	50.00 FS	*15.00 FS
60	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
61	1		*REAR BUMPER CHROME CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*REAR BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
63	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
64	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
65	1		*SPARE WHEEL PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
66	1		*REAR WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*20.00 FS
68	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
69	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
70	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
71	1		*REAR FENDER OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
72	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
73	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)**53,359.00****23,562.12**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					5,111.90	2,312.71
Total Parts (S\$)					48,247.10	21,249.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILL REPAIRS	New	400.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS &	New	2,400.00	1,800.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	1,400.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	120.00
6	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
7	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	120.00	20.00
8	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
9	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE R	New	200.00	60.00
10	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
11	TO RNR ALL AFFECTED SEAT BELTS TO FACILITATE REPAIRS	New	300.00	150.00
12	TO RNR DASHBOARD ASSY TO FACILITATE REPAIRS	New	600.00	0.00
13	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
14	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNIT ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	1,000.00	180.00
Gross Labour Cost (\$\$)			8,840.00	4,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >