

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21002907/RPA3Q2**Date:** 21/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900167783
Claimant Vehicle No :	GBD4637S	Insured Vehicle No :	YP9706H
Date of Loss:	01/03/2021	Nature of Claim:	TP
		Claim No:	6894838833SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD4637S		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD	Engine No:	ZD30342699K
	EURO 5 (A)		
Reg. Date:	30/10/2014 (Man. Year: 2014)	Chassis No:	JN1SC2F24Z0856628
Colour:	Grey	Odometer:	399311 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R13C (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 5/5 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	05/03/2021	
Date Inspected:	05/03/2021 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$31,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BRACKET	Bent	0.00 F	*- F
3	1		*REAR NUMBER PLATE LAMP	Scratched	0.00 F	*- F
4	1		*REVERSE SENSOR	Cut	0.00 F	*- F
5	2		*REAR END PANEL (LH/RH)	Repair	0.00 F	*- F
6	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
7	1		*TAILGATE	Buckled	0.00 F	*- F
8	1		*TAILGATE LOCK	Missing	0.00 F	*- F
9	2		*TAILGATE RUBBER (LH/RH)	Missing	0.00 F	*- F
10	2		*TAILGATE HINGE (LH/RH)	Dented	0.00 F	*- F
11	1		*SPARE TYRE	*Check	0.00 F	*- F
12	1		*REAR LH CHASSIS MEMBER	Repair	0.00 F	*- F
13	1		*REAR RH CHASSIS MEMBER	Repair	0.00 F	*- F
14	1		*TAILGATE ZINC SHEET	Buckled	0.00 F	*- F
15	1		*TAILGATE 70KM/H	Necessary	0.00 F	*- F
16	1		*TAILGATE NISSAN	Necessary	0.00 F	*- F
17	1		*TAILGATE 13 PAX	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >