

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002908/UVF3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00169862000
Claimant Vehicle No :	SKV4278T	Insured Vehicle No :	SCU8837D
Date of Loss:	02/03/2021	Nature of Claim:	TP
		Claim No:	SNM21D201211C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV4278T	Engine No:	R18A1730832
Make & Model:	HONDA STREAM, 1.7 (A)	Chassis No:	RN61027436
Reg. Date:	30/04/2007 (Man. Year: 2007)	Odometer:	178675 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,206.00	1,086.70	6,119.30	84.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	820.00	2,130.00	72.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,156.00	1,906.70	8,249.30	81.23
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	10,156.00	1,500.00	8,656.00	85.23

INSPECTION

Date of Assignment:	04/03/2021	
Date Inspected:	04/03/2021	Inspected At:
		PKS Automotive Pte Ltd (HQ) 8 Kaki Bukit Avenue 4 #01 – 52 Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV4278T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (DENTED)	Not Consistent With The Impact	328.00 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER	O/s Cracked	60.00 FL	*30.00 FL
3	1		*FRONT GRILLE ASSY	Not Necessary	318.00 FL	*- FL
4	1		*FRONT GRILLE EMBLEM	Not Necessary	54.00 FL	*- FL
5	1		*FRONT RH HEADLAMP	Scratched	780.00 FL	*780.00 FL
6	1		*FRONT RH HEADLAMP BRACKET	Cracked	45.00 FL	*45.00 FL
7	1		*FRONT RH FOG LAMP	Not Necessary	354.00 FL	*- FL
8	1		*FRONT RH FOG LAMP COVER	Not Necessary	96.00 FL	*- FL
9	1		*FRONT RH FENDER	Repair	586.00 FL	*- FL
10	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	94.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Not Necessary	566.00 FL	*- FL
12	1		*AIRCON CONDENSER	Not Necessary	894.00 FL	*- FL
13	1		*RADIATOR ASSY	Not Necessary	1,525.00 FL	*- FL
14	1		*FRONT RH KNUCKLE ARM	Not Necessary	367.00 FL	*- FL
15	1		*FRONT RH KNUCKLE BEARING	Not Necessary	242.00 FL	*- FL
16	1		*FRONT RH LOWER ARM	Not Necessary	426.00 FL	*- FL
17	1		*FRONT RH SHOCK ABSORBER	Not Necessary	615.00 FL	*- FL
18	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
19	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
20	1		*SET FRONT FENDER INNER TRIM CLIP	Necessary	30.00 FS	*30.00 FS
21	1		*RIM	Not Necessary	500.00 FS	*- FS
22	1		*BOT COOLANT	Not Necessary	60.00 FS	*- FS
23	1		*BOT BRAKE FUILD	Not Necessary	60.00 FS	*- FS
24	1		*FRONT BUMPER (\$665.40)(50%)	Torn	556.00 FS	*332.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,676.00	1,257.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,470.00	171.00
Total Parts (\$\$)	7,206.00	1,086.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	New	80.00	20.00
2	REMOVE,RENEW CONDENSER AND TOP UP GAS	New	150.00	0.00
3	REMOVE,RENEW RADIATOR AND TOP UP COOLANT	New	150.00	0.00
4	COMPUTERISED AND CHECK FROM WHEEL ALIGNMENT	New	200.00	0.00
5	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS	New	250.00	0.00
6	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,000.00	300.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	500.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			2,950.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >