



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 6550Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LH HEADLAMP ASSY (WCP)	CRACKED	1,172.00	1,172.00
1	LH HEADLAMP BRACKET (WCP)	NOT NECESSARY	236.60	-
	COST PLUS 10%		140.86	117.20
			1,549.46	1,289.20
	<b><u>LABOUR</u></b>			
	TO DISCONNECT & CHECK ELECTRICAL WIRING, WIRE SOCKET, ETC, REMOVE & REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		120.00	30.00
	TO REMOVE & REINSTALL FRONT BUMPER & TO INSTALL LHF NEW HEADLAMP.		220.00	150.00
			340.00	180.00
<b>GRAND TOTAL</b>			<b>1,889.46</b>	<b>1,469.20</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>				<b>1,469.20</b>
<b>LESS EXCESS</b>				<b>-500.00</b>
<b>NETT LIABILITY</b>				<b>969.20</b>

Report Ref No. CS/AWA21002910/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.