

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	R	lef:	CS3/ASM21002923/Qvf3e2	
	8 SHENTON WAY TOWERSINGAPOR	D	ate:	09/03/2021		
	ATTN : TAN JUN H	С	ode:	ASM		
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 6102H	Veh. Inspected		SLS 6601J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M034BO	Excess (\$)		0.00	
	Assign From	TAN JUN HONG	Assign Date		03/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 2	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6DJ2HAA01200146	Colour		BLUE	
	Odometer	30868 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	185/60 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	185/60 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	185/60 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
5. General Information						
	Accident Date	01/03/2021	Inspect Date / Tir	me	04/03/2021 (03:15 PM)	
	Survey held at	SENG HWEE MOTOR				
		BLK 1018, #01-350 YISHUN INDUSTRIAL PARK A SINGAPORE 768760				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21002923/Qvf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser