

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 737S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	TO REPAIR SEE LABOUR	1,399.20	-
1	SET TAILGATE "NISSAN" STICKER	NECESSARY	175.00	175.00
1	TAILGATE LOWER MEMBER	BENT	545.10	545.10
1	TAILGATE LOWER "L" PANEL N/S	TO REPAIR SEE LABOUR	165.00	-
1	TAILGATE LOWER "L" PANEL RUBBER N/S	SERVICEABLE	86.00	-
1	REAR LICENCE PLATE BRACKET	BENT	148.20	148.20
1	REAR SPARE TYRE BRACKET & CHAIN	DAMAGED	366.10	366.10
2	TAILLAMPS @\$208.00	CRACKED	416.00	416.00
	LESS 10% DISCOUNT		-	-165.04
			3,300.60	1,485.36
	SPECIAL NETT ITEMS			
1	SET TAILGATE 70KM/H & 13 PAX STICKER (SN)	NECESSARY	20.00	20.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR STEP PANEL (SN)	BENT	600.00	500.00
1	REAR STEP PANEL ALUMINIUM (SN)	BENT	500.00	300.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	14.00
1	SET TAILGATE ALUMINIUM RIVET (SN)	NECESSARY	50.00	50.00
			1,470.00	1,084.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND TAILGATE LOWER "L" PANEL N/S.		900.00	600.00
	TO PUTTY & SPRAY PAINTING.		900.00	600.00
			1,980.00	1,310.00
	GRAND TOTAL		6,750.60	3,879.36

Report Ref No. CS/TP21002925/Uqf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,100.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/TP21002925/Uqf3e2

CHUA KANG SENG
Licensed Appraiser