

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR17014036/KEA3Q2-1
Date: 11/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999995065
Claimant Vehicle No :	SLC5363L	Insured Vehicle No :	SLD4204P
Date of Loss:	16/07/2017	Nature of Claim:	TP
		Claim No:	7123387248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC5363L	Engine No:	1ZRX560049
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104547973
Reg. Date:	18/05/2016 (Man. Year: 2015)	Odometer:	21576 km
Colour:	Metallic Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,418.72	1,598.02	1,820.70	53.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,260.00	680.00	35.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,358.72	2,858.02	2,500.70	46.67
Approved Total (Overridden) (S\$)		2,250.00		

(S\$)	5,358.72	2,250.00	3,108.72	58.01
+ GST 7.00/7.00% (S\$)	375.11	157.50	217.61	58.01
Nett Amount (S\$)	5,733.83	2,407.50	3,326.33	58.01
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		2,767.50		
Liabe Amount (50.00%) (S\$)		1,383.75		

INSPECTION

Date of Assignment: 19/07/2017

Date Inspected: 21/07/2017

Estimated Period of Repair: 5.0 days

Inspected At:

City Auto Pte Ltd (HQ)
 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	917.40 FL	*- FL
2	1		*REAR DOOR RH	Repair	1,004.70 FL	*- FL
3	1		*SPORT RIM	Dented	1,644.00 FL	*1,644.00 FL
4	1		*REAR FENDER	Bent	486.70 FL	*486.70 FL
5	1		*REAR WHEEL BEARING	Not Necessary	328.30 FL	*- FL
6	2		*DOOR STICKER	Not Necessary	177.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,558.30	2,130.70
- List Item Discount on L Items 25.00/25.00% (\$)	1,139.58	532.68
Total Parts (\$)	3,418.72	1,598.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING,WELDING,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	750.00	600.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	950.00	600.00
3	COMPUTERISED WHEEL ALIGNMENT	New	60.00	60.00
4	TO REMOVE AND INSTALL DOOR GLASS	New	80.00	0.00
5	TO CHARGE REAR WHEEL BEARING	New	100.00	0.00
Gross Labour Cost (S\$)			1,940.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >