

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21002937/UPA3Q2
Date: 19/11/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SLR2815R	Insured Vehicle No :	GBK8189E
Date of Loss:	21/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000853

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2815R	Engine No:	P520449980
Make & Model:	MAZDA 3, 1.5 SEDAN AT LED EU6 (A)	Chassis No:	JM6BN22A8H0157152
Reg. Date:	08/08/2017 (Man. Year: 2017)	Odometer:	208306 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	APLUS 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	APLUS 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,319.04	1,870.00	449.04	19.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	770.00	1,120.00	59.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,209.04	2,640.00	1,569.04	37.28
Approved Total (Overridden) (S\$)		2,100.00		

	(S\$)	4,209.04	2,100.00	2,109.04	50.11
+ GST 7.00/7.00% (S\$)		294.63	147.00	147.63	50.11
Nett Amount (S\$)		4,503.67	2,247.00	2,256.67	50.11
+ Loss of Use (4.0 x S\$60.00/day) (S\$)			240.00		
	(S\$)		2,487.00		
Liabe Amount (50.00%) (S\$)			1,243.50		
+ Doc/Search Fee (S\$)			36.45		
Nett Liability (S\$)			1,279.95		
Global Sum Settlement (S\$)			1,250.00		

INSPECTION

Date of Assignment: 04/03/2021

Date Inspected: 04/03/2021

Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2021)
Parts: 143	MAZDA 3 1.5 SEDAN AT LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR2815R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FENDER -RH	Buckled	756.20 FL	*360.80 FL	
2	1		*FRONT FENDER DUST COVER -RH	Torn	124.40 FL	*119.30 FL	
3	1		*SET FRONT FENDER DUST COVER CLIPS -RH	Necessary	33.00 FL	*33.00 FL	
4	1		*FRONT HEADLAMP -RH	Scratched	773.30 FL	*773.30 FL	
5	1		*FRONT BUMPER	Torn	925.20 FL	*925.20 FL	
6	1		*FRONT BUMPER SIDE RETAINER -RH	Bent	39.70 FL	*39.70 FL	
7	1		*FRONT BUMPER FOG LAMP COVER -RH	Not Necessary	80.40 FL	*- FL	
8	1		*FRONT FENDER SUPPORT BRACKET -RH	Bent	86.20 FL	*86.20 FL	
9	1		*FRONT WASHER TANK	Not Necessary	80.40 FL	*- FL	
					Sub Total (S\$)	2,898.80	2,337.50
					- List Item Discount on L Items 20.00/20.00% (S\$)	579.76	467.50
					Total Parts (S\$)	2,319.04	1,870.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	300.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	ALIGNMENT	New	50.00	0.00
5	SPRAY PAINTING	New	820.00	420.00
			Gross Labour Cost (S\$)	770.00
			1,890.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >