

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002948/AVF3E2

Date: 08/09/2021

REFERENCE

Insured/Claimant: DHARMARAJ MELANCIA SNEGA LATHA
Date of Loss: 01/03/2021

Policy No: 1900009059
Nature of Claim: OD Claim No: 6232249957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7690R	Engine No:	CVK075880
Make & Model:	AUDI A4, 1.4 (A)	Chassis No:	WAUZZZF43KA029160
Reg. Date:	30/01/2019 (Man. Year: 2018)	Odometer:	9346 km
Colour:	Bronze		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$118,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,570.00	7,770.96	11,799.04	60.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,722.00	3,072.00	7,650.00	71.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,292.00	10,842.96	19,449.04	64.21
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	29,192.00	9,742.96	19,449.04	66.62
+ GST 7.00/7.00% (S\$)	2,043.44	682.01	1,361.43	66.62
Nett Amount (S\$)	31,235.44	10,424.97	20,810.47	66.62

INSPECTION

Date of Assignment: 04/03/2021

Date Inspected: 04/03/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	36.00 FS	*- FS
4	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER CTR	Not Necessary	210.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE LH	Not Necessary	63.00 FS	*- FS
7	1		*FRONT BUMPER RADIATOR GRILLE	Not Necessary	1,332.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Not Necessary	135.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	36.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION BRACKET LH	Not Necessary	228.00 FS	*- FS
14	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
15	2		*FRONT BUMPER SUPPORT BRACKET - LH / RH	Not Necessary	58.00 FS	*- FS
16	1		*CAUTION STICKER LABEL	Not Necessary	14.00 FS	*- FS
17	1		*AIRCON STICKER LABEL	Not Necessary	8.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR INNER / OUTER	Not Necessary	244.00 FS	*- FS
19	4		*FRONT PARKING SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
20	1		*HIGH TONE HORN LH	Not Necessary	126.00 FS	*- FS
21	1		*HIGH TONE HORN SPRING SHACKLE LH	Not Necessary	29.00 FS	*- FS
22	1		*FRONT FENDER LH	Repair	767.00 FS	*- FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
24	1		*FRONT BUMPER CLOSING ELEMENT LH	Not Necessary	72.00 FS	*- FS
25	1		*FRONT BUMPER BRACKET LH	Not Necessary	35.00 FS	*- FS
26	1		*FRONT BUMPER BRACKET LH	Not Necessary	49.00 FS	*- FS
27	1		*FRONT BUMPER BRACE LH	Not Necessary	118.00 FS	*- FS
28	1		*FRONT WHEEL HOUSING LINER	Not Necessary	240.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	233.00 FS	*- FS
30	1		*FRONT FENDER WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
31	1		*FRONT FENDER END PLATE LH	Not Necessary	35.00 FS	*- FS
32	1		*FRONT FENDER STONE CHIP GUARD LH	Not Necessary	51.00 FS	*- FS
33	1		*FRONT FENDER OUTER LEDGE COVER	Not Necessary	31.00 FS	*- FS
34	2		*FRONT FENDER INNER LEDGE COVER	Not Necessary	23.00 FS	*- FS
35	3		*FRONT FENDER IMPACT PROTECTION - LH / RH / CTR	Not Necessary	84.00 FS	*- FS
36	1		*LED HEADLIGHT	Cracked	7,693.00 FS	*6,154.40 FS
37	2		*CONTROL MODULE FOR MAIN LIGHT SYSTEM	Not Necessary	761.00 FS	*- FS
38	4		*CONTROL MODULE FOR LIGHT CONTROL SYSTEM	Not Necessary	751.00 FS	*- FS
39	1		*HEADLIGHT DRAIN HOSE	Not Necessary	36.00 FS	*- FS
40	1		*HEADLIGHT LIFT CYLINDER LH	Damaged	210.00 FS	*167.60 FS
41	1		*HEADLIGHT LIFT CYLINDER BRACKET LH	Not Necessary	6.00 FS	*- FS
42	6		*HEADLIGHT WASHER HOSE	Not Necessary	93.00 FS	*- FS
43	1		*RADIATOR CARRIER	Not Necessary	1,016.00 FS	*- FS
44	1		*RADIATOR SUPPORT BRACKET	Not Necessary	38.00 FS	*- FS
45	1		*COOLANT	Not Necessary	179.00 FS	*- FS
46	1		*RADIATOR OUTER DUCT	Not Necessary	28.00 FS	*- FS
47	1		*RADIATOR INNER DUCT	Not Necessary	12.00 FS	*- FS
48	2		*RADIATOR AIR GUIDE UPPER / LOWER	Not Necessary	38.00 FS	*- FS
49	1		*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
50	1		*SUNDRIES	Necessary	300.00 FS	*19.36 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **19,570.00** **7,770.96**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	500.00
5	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER	New	2,900.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,722.00	3,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >