



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD			Ref: CC4/ASM21002953/Aga3q2 Date: 16/07/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 8896L	Veh. Inspected	PC 8622Y
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M034F1	Excess (\$)	0.00
	Assign From		Assign Date	04/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE COMMUTER	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GDH2232001955	Colour	WHITE
	Odometer	66205 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MICHELIN	6 mm
	L/H Front Tyre	195 R15C	MICHELIN	6 mm
	R/H Rear Tyre	195 R15C	MICHELIN	6 mm
	L/H Rear Tyre	195 R15C	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/03/2021	Inspection Date	05/03/2021
	Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	