

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG21002955/T1PS3Q2

**Date:** 05/05/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070156597

**Claimant**  
**Vehicle No :** SHD3526P **Insured Vehicle No :** SJW1629R

Date of Loss: 04/03/2021 Nature of Claim: TP Claim No: 1746334875SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                       |             |                   |
|-----------------------------|---------------------------------------|-------------|-------------------|
| Reg No:                     | SHD3526P                              | Engine No:  | G4LEJU081798      |
| Make & Model:               | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) | Chassis No: | KMHC851CVKU107562 |
| Reg. Date:                  | 13/09/2018 (Man. Year: 2018)          | Odometer:   | 387990 km         |
| Colour:                     | Blue                                  |             |                   |
| Engine Capacity:            | 1580 cc                               |             |                   |
| Market Value/New Car Price: | N/A                                   |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>     |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 195/65 R15   | Rear Tyre Size:  | 195/65 R15   |
| Front Left Side:  | Davanti 6 mm | Rear Left Side:  | Davanti 6 mm |
| Front Right Side: | Davanti 6 mm | Rear Right Side: | Davanti 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 3,211.92          | 3,129.52          | 82.40             | 2.57          |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 1,950.00          | 1,205.00          | 745.00            | 38.21         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>5,161.92</b>   | <b>4,334.52</b>   | <b>827.40</b>     | <b>16.03</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,400.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 5,161.92          | 3,400.00          | 1,761.92          | 34.13         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 361.33            | 238.00            | 123.33            | 34.13         |
| <b>Nett Amount (S\$)</b>                        | <b>5,523.25</b>   | <b>3,638.00</b>   | <b>1,885.25</b>   | <b>34.13</b>  |
| <b>+ Loss of Use (4.5 x S\$50.00/day) (S\$)</b> |                   | 225.00            |                   |               |
| <b>+ Car Rental (4.5 x S\$125.19/day) (S\$)</b> |                   | 563.36            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>4,428.36</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>4,400.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 04/03/2021

Date Inspected: 04/03/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *EMBLEM -HYBRID             | Necessary     | 24.30 FL    | *24.30 FL    |
| 2   | 1   |          | *EMBLEM -IONIQ              | Necessary     | 31.30 FL    | *31.30 FL    |
| 3   | 1   |          | *COVER -RR BUMPER           | Deformed      | 459.40 FL   | *459.40 FL   |
| 4   | 1   |          | *MOULDING ASSY -RR BUMPER C | Deformed      | 451.25 FL   | *451.25 FL   |
| 5   | 10  |          | *BUMPER COVER CLIP REAR     | Necessary     | 22.00 FL    | *22.00 FL    |
| 6   | 1   |          | *PANEL ASSY -TAIL GATE      | Bent          | 2,480.40 FL | *2,480.40 FL |
| 7   | 1   |          | *SYMBOL MARK-H              | Necessary     | 28.00 FL    | *28.00 FL    |
| 8   | 1   |          | *ANTENNA ASSY -SMARTKEY     | Not Necessary | 40.50 FL    | *- FL        |
| 9   | 1   |          | *LAMP ASSY -REAR FOG        | Cut           | 201.50 FL   | *201.50 FL   |
| 10  | 2   |          | *WINDSCREEN AHESIVE -310MLC | Necessary     | 46.00 FS    | *46.00 FS    |
| 11  | 1   |          | *REAR BOOT LOGO CTPL        | Necessary     | 30.00 FS    | *30.00 FS    |
| 12  | 1   |          | *REAR BOOT TEL NUMBER CTPL  | Necessary     | 30.00 FS    | *30.00 FS    |
| 13  | 1   |          | *APP LOGO REAR BONNET CTRL  | Necessary     | 40.00 FS    | *40.00 FS    |
| 14  | 1   |          | *PROTECTOR MAT              | Not Necessary | 50.00 FS    | *- FS        |
| 15  | 1   |          | *NUMBER PLATE REAR          | Cracked       | 25.00 FS    | *25.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>3,959.65</b> | <b>3,869.15</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 747.73          | 739.63          |
| <b>Total Parts (\$\$)</b>                                  | <b>3,211.92</b> | <b>3,129.52</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                 | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                             |          |                 |                 |
| 1                               | PANEL BEATING               | New      | 1,100.00        | 525.00          |
| 2                               | SPRAYPAINT CHARGE           | New      | 600.00          | 500.00          |
| 3                               | RENEW REAR WINDSCREEN GLASS | New      | 120.00          | 120.00          |
| 4                               | REMOVE/REFIX REVERSE SENSOR | New      | 80.00           | 30.00           |
| 5                               | CHECK ALL LIGHTING          | New      | 50.00           | 30.00           |
| <b>Gross Labour Cost (\$\$)</b> |                             |          | <b>1,950.00</b> | <b>1,205.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >