

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21002964/DVD3E2

Date: 14/10/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : FBL1529Z **Insured Vehicle No :** UNKNOWN
Date of Loss: 18/12/2020 Nature of Claim: TP Claim No: CDMCG20002052

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL1529Z**
Make & Model: PGO I ME, 148cc 150 WEL BIKE 3-WHEELER Engine No: C5H17945
Reg. Date: 30/06/2016 (Man. Year: 2016) Chassis No: RFVBF3C5CG1000241
Colour: Red Odometer: 0 km
Engine Capacity: 148 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R12 Rear Tyre Size: 4.80-12
Front Left Side: Maxxis 2 mm Rear Left Side: Maxxis 2 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,250.00	1,320.00	930.00	41.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	130.00	630.00	82.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,010.00	1,450.00	1,560.00	51.83
Approved Total (Overridden) (S\$)		1,150.00		
Nett Amount (S\$)	3,010.00	1,150.00	1,860.00	61.79

INSPECTION

Date of Assignment: 04/03/2021
Date Inspected: 05/03/2021 Inspected At: Sg 98 Motor Enterprise (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
#01-21
Singapore 569622
Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Oct 2021)	
Parts:	N/A	PGO I ME 148cc 150 WEL BIKE 3-WHEELER (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL1529Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR RIM	Cracked / Broken	480.00 FL	*480.00 FL
2	2		*BRAKE CALIPER	Not Necessary	380.00 FL	*- FL
3	2		*REAR DRIVE SHAFT	Bent	390.00 FL	*390.00 FL
4	1		*LH REAR FENDER	Broken	250.00 FL	*250.00 FL
5	2		*REAR DRIVE SHAFT BEARING	Necessary	180.00 FL	*180.00 FL
6	2		*REAR SHOCK ABSORBER	Serviceable	420.00 FL	*- FL
7	1		*SET REAR SIDE CARRIER BOX	Cut	360.00 FS	*150.00 FS
					Sub Total (\$\$)	2,460.00 1,450.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	210.00 130.00
					Total Parts (\$\$)	2,250.00 1,320.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	60.00	0.00
2	REMOVE & REPLACE PARTS, ALIGN & ETC	New	250.00	50.00
3	REPLACE DRIVE SHAFT / BEARING, SHOCK ABSORBER ASSEMBLY, REAR RIM	New	450.00	80.00
Gross Labour Cost (\$)			760.00	130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >