

ASS. BY:

REF: CS EGI21002964 Dvd3

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / TPWS / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work top m/s _____

of _____

Insured UNKNOWN

Policy # _____

Claims b. CDMCG20002052

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBL15292

Yr Regn: June, 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: P.G.O. IME 150

C.C. 148

Colour Red

A/C: Insured / Std / NI / NA

Sp. Reading N.A.

T/Radio: Insured / Std / NI / NA

Eng/No: -

C5H17945

C/No: RFVBF3C5LG2000241

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R12

R: 4.80 - 12

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUZUKI

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

mm

L/Bal.

2

mm

D.O.A. 18/12/2020

D.O.L. 05/03/2021

Survey held at

SG 98 AMK

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

H/S Rev 7 O/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Blgo XE 6668 Z

delay in survey as pending Traffic Police to provide claimant with the vehicle number of OI. After accident, vehicle towed to workshop and parked there till survey. Towing receipt uploaded in VIEWS.

12/10/21. Juncu 2/5, 150/- with 3 days of rev (Red 1860,61%)

Date/Time, File Pass to?

: Preli. Report

1)

Date/Time, File Return to?

: Final Report

2) 12/10/21-typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format: Merimen

LUMED Sum / L.B.P. % LS \$1150

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 8th April 2021

To : LKK

By Fax:

Attn : Bryan

Tel :

VEHICLE NO : FBL 1529Z

P.G.O. IME 150 WEL Bike 3-Wheeler

ACCIDENT DATE: 18/12/2020

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Rear Rim <i>crack/broken</i>	2	480.00 ✓
2 Brake Caliper <i>HY</i>	2	380.00 X
3 Rear Drive Shaft <i>rst</i>	2	390.00 ✓
4 LH Rear Fender <i>broken</i>	1	250.00 ✓
5 Rear Drive Shaft Bearing <i>HYC</i>	2	180.00 ✓
6 Rear shock Absorber <i>SVC</i>	2	420.00 X
Sub-Total		2,100.00
Less 10%		210.00
Sub-Total		1,890.00

1300.00

1170.00

VEHICLE NO : FBL 1529Z

P.G.O. IME 150 WEL Bike 3-Wheeler

Nett items

- 1 Towing fees ~~400~~
- 2 Remove & replace parts, align & etc
- 3 Replace Drive shaft/bearing, shock absorber assembly, Rear Rim
- 4 Rear Side Carrier Box ~~cut~~

1 set

Sub-Total

Nett Total

60.00 X
250.00 50/-
450.00 80/-
360.00 150/-

1,120.00

3,010.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 Motor Pte Ltd

1450.00

4/5 1150/-

05/03/2022 @ 1200hrs

NA Author

4/5 hrs 3 days.

Ryan

LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: