

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21002965/UBS3Q2
Date: 09/06/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SFN7070G	Insured Vehicle No :	SLH5138U
Date of Loss:	04/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000992

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFN7070G		
Make & Model:	MERCEDES-BENZ A200, 1.3 (A)	Engine No:	28291480059469
Reg. Date:	02/04/2020 (Man. Year: 2019)	Chassis No:	WDD1771872W011875
Colour:	Silver	Odometer:	9888 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Hankook 8 mm	Rear Left Side:	Hankook 8 mm
Front Right Side:	Hankook 8 mm	Rear Right Side:	Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,919.00	1,444.50	3,474.50	70.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,245.00	1,260.00	985.00	43.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,164.00	2,704.50	4,459.50	62.25
+ GST 7.00/7.00% (S\$)	501.48	189.32	312.16	62.25

Nett Amount (S\$)	7,665.48	2,893.82	4,771.66	62.25
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
Nett Liability (S\$)		3,343.82		
Global Sum Settlement (S\$)		3,200.00		

INSPECTION

Date of Assignment: 05/03/2021

Date Inspected: 12/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Specialists Motor Pte Ltd (HQ)
 Blk 3018A Ubi Road 1, #01-24/25/26
 Singapore 408711

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2021)
Parts:	144	MERCEDES-BENZ A200 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFN7070G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Dented	1,330.00 F	*1,330.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
3	2		*REAR BUMPER SIDE RETAINER L& RH	Serviceable	186.00 F	*- FL
4	1		*REAR BUMPER REFLECOTR RH	Cracked	35.00 F	*35.00 FL
5	1		*REAR BUMPER SENSOR RH	Shorted	180.00 F	*180.00 FL
6	1		*REAR BUMPER TOWING COVER	Not Necessary	144.00 F	*- FL
7	1		*REAR BUMPER SPONGE RH	Not Necessary	135.00 F	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	490.00 F	*- FL
9	1		*REAR BUMPER BRACKET RH	Serviceable	105.00 F	*- FL
10	1		*REAR BUMPER DIFFUSER	Serviceable	485.00 F	*- FL
11	1		*REAR BUMPER CHROME (CENTRE)	Not Necessary	300.00 F	*- FL
12	2		*REAR BUMPER EXHAUST CHROME L&RH	Not Necessary	304.00 F	*- FL
13	1		*ENGINE UNDER COVER	Not Necessary	290.00 F	*- FL
14	1		*REAR LAMP ASSY RH	Not Necessary	600.00 F	*- FL
15	1		*REAR LAMP PANEL RH	Repair	275.00 F	*- FL
					Sub Total (\$\$)	4,919.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	160.50
					Total Parts (\$\$)	1,444.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT OUT ,RENEW KNOCKING & WELDING REAR LAMP PANEL RH ,REAR FENDER RH ,REMOVE & INSTALL ALL DAMAGE PARTS & RE-ALIGN BODY	New	980.00	600.00
2	REMOVE & INSTALL REAR BUMPER SENSOR	New	100.00	40.00
3	TUFF-KOTE ON DAMAGE PARTS	New	40.00	0.00
4	SPRAY PAINTING ON DAMAGE PARTS	New	1,080.00	600.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	45.00	20.00
Gross Labour Cost (\$)			2,245.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >