

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 680G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL SUB-ASSY, FENDER REAR LH (DISC 25%)	CRUMPLED	824.80	618.60
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PANEL SUB-ASSY, FRONT DOOR LH	SERVICEABLE	1,249.60	-
1	DOOR OUTER HANDLE FRONT, LH	SERVICEABLE	378.90	-
1	PIXEL STICKER	SERVICEABLE	60.00	-
1	HINGE ASSY, REAR DOOR, UPPER LH	SERVICEABLE	83.30	-
1	HINGE ASSY, REAR DOOR, LOWER LH	SERVICEABLE	73.30	-
1	CHECK ASSY, REAR DOOR	SERVICEABLE	153.50	-
1	MOULDING ASSY, BODY ROCKER PANEL, LH	TO REPAIR SEE LABOUR	576.00	-
1	PANEL SUB-ASSY, REAR DOOR, LH	TO REPAIR SEE LABOUR	1,243.90	-
			4,703.30	678.60
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF MOULDING ASSY, BODY ROCKER PANEL, LH AND PANEL SUB-ASSY, REAR DOOR, LH.		845.00	400.00
	SPRAY PAINT.		1,314.00	500.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,739.00	950.00
	GRAND TOTAL		7,442.30	1,628.60





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,300.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC21002966/Qvf3e2

Ja

OI SUN PIN

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser