

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	Re	ef:	CS3/LPC21002968/T1qf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Da	ite:	06/04/2021	
			Co	de:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YP 9998G	Veh. Inspected		SKZ 8576K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VC05/024294	Excess (\$)		0.00	
	Assign From	ON GLI LI	Assign Date		05/03/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA AXIO	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	NRE1610010108	Colour		WHITE	
	Odometer	293405 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	KAPSEN		6 mm	
	L/H Front Tyre	185/60 R15	KAPSEN		6 mm	
	R/H Rear Tyre	185/60 R15	KAPSEN		6 mm	
	L/H Rear Tyre	185/60 R15	KAPSEN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S REAR PORTION.				
5.	General Information					
	Accident Date	04/03/2021	Inspect Date / Tim	ne	08/03/2021 ( 01:20 PM )	
	Survey held at	FREESION AUTODRIVE	•			
		25 KAKI BUKIT ROAD 4 SYNERGY @ KB #03-33 SINGAPORE 417800				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21002968/T1qf3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**