

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002975/KPS3Q2
Date: 25/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900085962
Claimant Vehicle No :	SLD7946L	Insured Vehicle No :	SLZ1648X
Date of Loss:	25/02/2021	Nature of Claim:	TP
		Claim No:	0038456048SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD7946L	Engine No:	2AZ4A15909
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR500194508
Reg. Date:	29/06/2016 (Man. Year: 2015)	Odometer:	99083 km
Colour:	Metallic Pearl White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,986.80	4,002.87	983.93	19.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,780.00	710.00	28.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,476.80	5,782.87	1,693.93	22.66
+ GST 7.00/7.00% (S\$)	523.38	404.80	118.58	22.66

Nett Amount (S\$)	8,000.18	6,187.67	1,812.51	22.66
+ Car Rental (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,939.67		

INSPECTION

Date of Assignment: 05/03/2021

Date Inspected: 08/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING COMPLETE	Necessary	101.60 FL	*101.60 FL
2	1		*TAILGATE	Bent	1,939.50 FL	*1,753.60 FL
3	1		*TAILGATE EMBLEM	Necessary	59.80 FL	*59.80 FL
4	1		*TAILGATE ESTIMA LOGO	Necessary	49.75 FL	*49.75 FL
5	1		*TAILGATE AERAS LOGO	Necessary	55.68 FL	*55.68 FL
6	1		*TAILGATE NO PLATE GARNISH	Serviceable	200.10 FL	*- FL
7	1		*TAILGATE LOCK	Dented	490.30 FL	*490.30 FL
8	1		*TAILGATE RUBBER	Necessary	371.70 FL	*371.70 FL
9	1		*TAILGATE INNER TRIMBOARD	Serviceable	501.70 FL	*- FL
10	1		*REAR BUMPER	Buckled	622.10 FL	*622.10 FL
11	2		*REAR BUMPER BRACKET OUTER LH & RH	Serviceable	115.40 FL	*- FL
12	2		*REAR BUMPER BRACKET INNER LH & RH	Serviceable	90.80 FL	*- FL
13	12		*REAR BUMPER CLIPS	Necessary	50.40 FL	*50.40 FL
14	1		*REAR BUMPER KEYLESS ANTENNA	Serviceable	191.50 FL	*- FL
15	2		*REAR BUMPER SPONGE LH & RH	Bent	159.20 FL	*159.20 FL
16	1		*REAR END PANEL	Bent	755.40 FL	*755.40 FL
17	1		*REAR END PANEL GARNISH TOP	Buckled	280.10 FL	*280.10 FL
18	1		*REAR END PANEL GARNISH BOTTOM	Buckled	194.20 FL	*194.20 FL
19	5		*REAR END PANEL GARNISH CLIPS	Not Necessary	26.50 FL	*- FL
20	1		*LAST ROW SEAT FRAME RH (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*LAST ROW SEAT FRAME RH (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*LAST ROW CORNER TRIM INNER RH (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*LAST ROW CORNER TRIM OUTER RH (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*LAST ROW BRACKET COVER RH (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
26	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
27	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
28	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,550.73	5,238.83
- List Item Discount on L Items 25.00/25.00% (\$)	1,563.93	1,235.96
Total Parts (\$)	4,986.80	4,002.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE AND REINSTALL CUSHION SEATS ,BACKREST ,INNER TRIM ,GARNISH ,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	180.00	100.00
3	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
4	TO DISMANTLE & INSTALL CAMERA	New	60.00	30.00
5	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
6	TO RESET ENGINE TAILGATE	New	350.00	0.00
7	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	60.00
8	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD REAR END PANEL TO KNOCK & REPAIR REAR BOOT ,REAR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	800.00	700.00
9	TO SPRAY TAILGATE ,REAR BUMPER ,RR END PANEL	New	800.00	660.00
Gross Labour Cost (\$\$)			2,490.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >