

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 1073K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FORK TUBE LH (CONSISTENT)	DISTORTED	280.00	280.00
1	HANDLE BAR (CONSISTENT)	SERVICEABLE	120.00	-
1	CLUTCH LEVER (CONSISTENT)	CUT	85.00	85.00
1	MIRROR LH (CONSISTENT)	N/S CUT	85.00	42.50
1	SET BALANCER (CONSISTENT)	N/S CUT	150.00	75.00
1	SET CRASH BAR (CONSISTENT)	CUT	320.00	320.00
1	FRONT LH SIGNAL (CONSISTENT)	CUT	80.00	80.00
1	FRONT MUDGUARD (CONSISTENT)	CUT	195.00	195.00
1	FRONT LH SIDE PANEL -TOP (CONSISTENT)	CUT	195.00	195.00
1	FRONT LH LOWER PANEL-LH(CONSISTENT)	CRACKED	185.00	185.00
1	GEAR PEDAL (CONSISTENT)	BENT	68.00	68.00
1	FRONT FOOTREST -LH (CONSISTENT)	BENT	78.00	78.00
1	REAR FOOTREST -LH (CONSISTENT)	NOT NECESSARY	78.00	-
1	BOX RACK /BRACKET (CONSISTENT)	CUT / BENT	120.00	120.00
1	REAR TAIL PANEL (CONSISTENT)	CUT / MTG BROKEN	180.00	180.00
1	SIGNAL SWITCH (CONSISTENT)	BROKEN	90.00	90.00
	LESS 10% DISCOUNT		-230.90	-199.35
			2,078.10	1,794.15
	SPECIAL NETT ITEMS			
1	REAR FRAME ALIGNMENT(SN)(CONSISTENT)	NECESSARY	250.00	150.00
1	BODY STICKER (SN)(CONSISTENT)	NECESSARY	150.00	80.00
1	REAR BOX -KAPPA (SN)(CONSISTENT)	CUT	480.00	300.00
1	IU UNIT (SN)(CONSISTENT)	SERVICEABLE	170.00	-
			1,050.00	530.00
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.		250.00	150.00
	REMOVE FORK & TOP UP FORK OIL.		120.00	80.00

Report Ref No. CC4/ASM21002977/Dgs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TOUCH UP PAINT WORK.		200.00	80.00
			610.00	310.00
	GRAND TOTAL		3,738.10	2,634.15

RECOMMENDED COST OF LUMP SUM REPAIRS	2,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM21002977/Dgs3q2



ANG BRYAN TANI

Automotive Assessor / Investigator