

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002986/QBA3Q2
Date: 07/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700082391
Claimant Vehicle No :	SLR2481U	Insured Vehicle No :	SLT8872A
Date of Loss:	27/02/2021	Nature of Claim:	TP
		Claim No:	6983026052SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2481U		
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Engine No:	1NZR440858
Reg. Date:	04/08/2017 (Man. Year: 2016)	Chassis No:	NHP1707060128
Colour:	Silver	Odometer:	293420 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,629.50	2,362.75	2,266.75	48.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,280.00	1,810.00	58.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,719.50	3,642.75	4,076.75	52.81
+ GST 7.00/7.00% (S\$)	540.37	254.99	285.38	52.81

Nett Amount (S\$)	8,259.87	3,897.74	4,362.13	52.81
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,299.74		
Global Sum Settlement (S\$)		4,100.00		

INSPECTION

Date of Assignment: 05/03/2021

Date Inspected: 05/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
 60 Jalan Lam Huat, #04-35/36 Carros Centre
 Singapore 737569

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,470.00 FL	*1,180.00 FL
2	1		*REAR TAILGATE WEATHERSTRIP	Crumpled	360.00 FL	*360.00 FL
3	1		*REAR TAILGATE LOCK ASSY	Jammed	504.00 FL	*412.00 FL
4	1		*REAR TAILGATE LOCK CATCH	Serviceable	64.80 FL	*- FL
5	1		*REAR TAILGATE CENTER GARNISH HOLDER	Repair	342.00 FL	*- FL
6	1		*REAR TAILGATE TOYOTA LOGO	Necessary	60.00 FL	*60.00 FL
7	1		*REAR TAILGATE HYBRIDE EMBLEM	Necessary	86.00 FL	*86.00 FL
8	1		*REAR END PANEL	Repair	828.00 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Serviceable	250.00 FL	*- FL
10	1		*REAR BUMPER COVER	Crumpled	900.00 FL	*750.00 FL
11	1		*REAR BUMPER LH BRACKET	Serviceable	90.00 FL	*- FL
12	1		*REAR BUMPER RH BRACKET	Serviceable	90.00 FL	*- FL
13	1		*REAR BUMPER CENTER BLACK PAD	Scratched	288.00 FL	*209.00 FL
14	1		*REAR BUMPER LH REFLECTOR	Serviceable	133.20 FL	*- FL
15	1		*KEYLESS SMART BUZZER ANTENA	Serviceable	120.00 FL	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
17	1		*SET REVERSE SENSOR	Serviceable	260.00 FS	*- FS
18	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,026.00	3,127.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,396.50	764.25
Total Parts (\$)	4,629.50	2,362.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	120.00	120.00
2	TRANSFER TAILGATE MECHANISM UPHOLSTERY SEATS	New	120.00	60.00
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR BUMPER ,END PANEL AND SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS ,ALSO INCLUDE STRAIGHTENNING OF BOTH REAR CHASSIS MEMBERS AND FLOOR PANEL	New	1,250.00	600.00
4	TO RESPRAY REAR TAILGATE ,REAR END PANEL,SPARE TYRE PANEL ,REAR BUMPER ,ROOF TOP AND BOTH REAR FENDERS	New	1,000.00	500.00
5	TO CONDUCT & STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENTS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
6	TO DEACTIVATE AND ACTIVE HIGH VOLTAGE BATTERY AS A SFACTY PRECAUTIONS	New	300.00	0.00
Gross Labour Cost (S\$)			3,090.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >