

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21002989/GRA3Q2  
**Date:** 29/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993598
<b>Claimant Vehicle No :</b>	SHC1718X	<b>Insured Vehicle No :</b>	SMC6294J
Date of Loss:	04/03/2021	Nature of Claim:	TP
		Claim No:	1469723106SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC1718X</b>		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS054232
Reg. Date:	19/07/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU403560634
Colour:	Blue	Odometer:	494977 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,595.40	3,672.67	922.73	20.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	630.00	550.00	46.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,775.40</b>	<b>4,302.67</b>	<b>1,472.73</b>	<b>25.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		

## Adjuster Report

	(S\$)	5,775.40	3,450.00	2,325.40	40.26
<b>+ GST 7.00/7.00% (S\$)</b>		404.28	241.50	162.78	40.26
<b>Nett Amount (S\$)</b>		<b>6,179.68</b>	<b>3,691.50</b>	<b>2,488.18</b>	<b>40.26</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>			200.00		
<b>+ Car Rental (4.0 x S\$125.40/day) (S\$)</b>			501.60		
<b>+ Doc/Search Fee (S\$)</b>			7.49		
<b>Nett Liability (S\$)</b>			<b>4,400.59</b>		

INSPECTION

Date of Assignment: 05/03/2021

Date Inspected: 05/03/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER FRONT BUMPER	Cut	499.90 FL	*499.90 FL	
2	10		*BUMPER PIECE	Necessary	22.00 FL	*22.00 FL	
3	1		*FENDER SUB-ASSY FRONT LH	Not Necessary	945.30 FL	*- FL	
4	1		*EMBLEM SIDE PANEL (HYBRID)	Not Necessary	86.50 FL	*- FL	
5	1		*LINER FRONT FENDER LH	Not Necessary	198.50 FL	*- FL	
6	1		*UNIT ASSY HEADLAMP LH	Scratched	3,455.00 FL	*3,455.00 FL	
7	1		*LAMP ASSY FOG LH	Broken	920.00 FL	*920.00 FL	
					<b>Sub Total (\$\$)</b>	<b>6,127.20</b>	<b>4,896.90</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,531.80	1,224.23
					<b>Total Parts (\$\$)</b>	<b>4,595.40</b>	<b>3,672.67</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	550.00	350.00
2	SPRAYPAINT ON AFFECTED AREA	New	530.00	250.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >