

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21002991/UVD3Q2  
**Date:** 22/03/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00100872000	
Claimant Vehicle No :	GBJ6889L	Insured Vehicle No :	YP9791K	
Date of Loss:	19/02/2021	Nature of Claim:	TP	Claim No: SNM21D201231C02/TANKAHLEONG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ6889L		
Make & Model:	NISSAN NV350, 2.5 (A)	Engine No:	YD25052676B
Reg. Date:	23/07/2019 (Man. Year: 2019)	Chassis No:	JN1MC2E26Z0031310
Colour:	White/Blue	Odometer:	80508 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,426.47	2,929.48	3,496.99	54.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	760.00	1,190.00	61.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,376.47</b>	<b>3,689.48</b>	<b>4,686.99</b>	<b>55.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,950.00</b>		
	(S\$)	8,376.47	2,950.00	5,426.47
<b>+ GST 7.00/7.00% (S\$)</b>	586.35	206.50	379.85	64.78
<b>Nett Amount (S\$)</b>	<b>8,962.82</b>	<b>3,156.50</b>	<b>5,806.32</b>	<b>64.78</b>

### INSPECTION

Date of Assignment:	05/03/2021	
Date Inspected:	08/03/2021	Inspected At: Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 19 Mar 2021)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ6889L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,213.70 FN	*1,816.70 FN
2	1		*TAILGATE WEATHERSTRIPE	Not Necessary	149.40 FN	*- FN
3	1		*TAILGATE OUTER CHROME MOULDING	Scratched	629.50 FN	*535.70 FN
4	1		*TAILGATE LOCK	Not Necessary	310.60 FN	*- FN
5	1		*TAIL LAMP ASSY LH	Cracked	262.50 FN	*224.80 FN
6	1		*TAIL LAMP ASSY RH	Not Necessary	262.50 FN	*- FN
7	1		*REAR BUMPER (DENTED)	Not Consistent With The Impact	745.90 FN	*- FN
8	1		*REAR BUMPER SIDE RETAINER (LH)	Not Necessary	27.20 FN	*- FN
9	1		*REAR BUMPER SIDE RETAINER (RH)	Not Necessary	27.20 FN	*- FN
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	194.80 FN	*- FN
11	10		*REAR BUMPER CLIPS	Not Necessary	45.00 FN	*- FN
12	1		*REAR END PANEL (NPA)	Repair	0.00 FN	*- FN
13	1		*LTA STICKER (70KM/H)	Necessary	25.00 FS	*10.00 FS
14	1		*LTA STICKER 8 PAX	Necessary	25.00 FS	*10.00 FS
15	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
16	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
17	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
18	1		*REAR WINDSCREEN GLASS ADVERTISEMENT (CUT)	Not Consistent With The Impact	550.00 FS	*- FS
19	1		*TAILGATE ADVERTISEMENT STICKER	Necessary	550.00 FS	*550.00 FS
20	1		*REAR BUMPER ADVERTISEMENT STICKER (SCRATCHED)	Not Consistent With The Impact	580.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,913.30</b>	<b>3,187.20</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	486.83	257.72
<b>Total Parts (\$\$)</b>	<b>6,426.47</b>	<b>2,929.48</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	800.00	300.00
2	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	140.00	100.00
3	TO REMOVE & INSTALL ALL TAILGATE FITTING	New	80.00	60.00
4	TO DETACH & RENEW REVERSE SENSOR	New	40.00	0.00
5	TO APPLY ANTI RUST COATING ON AFFECTED AREAS	New	60.00	30.00
6	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	20.00
7	TO SPRAY PAINT ON AFFECTED AREAS	New	800.00	250.00
Gross Labour Cost (S\$)			1,950.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >