

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21003003/R1PS3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800124387
Claimant Vehicle No :	SMX1436P	Insured Vehicle No :	SME9004A
Date of Loss:	04/03/2021	Nature of Claim:	TP
		Claim No:	8171664699SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX1436P	Engine No:	CZP249023
Make & Model:	VOLKSWAGEN PASSAT, 2.0 TFSI (A)	Chassis No:	WVWZZZ3CZLE144146
Reg. Date:	28/12/2020 (Man. Year: 2020)	Odometer:	3796 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,946.02	100.00	1,846.02	94.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,120.00	3,560.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,626.02	2,220.00	5,406.02	70.89
+ GST 7.00/7.00% (S\$)	533.82	155.40	378.42	70.89

Nett Amount (S\$)	8,159.84	2,375.40	5,784.44	70.89
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,762.60		

INSPECTION

Date of Assignment: 10/03/2021

Date Inspected: 10/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STOSSFANGERABDECKUNG GRUN FRT BUMPER	Repair	1,617.42 FS	*- FS
2	1		*1 SATZ GEBERHALTER SENSOR BRACKET	Not Necessary	44.68 FS	*- FS
3	1		*2K-PLASTIC ADHESIVE	Serviceable	78.91 FS	*- FS
4	1		*BONDING AGENT FOR PLASTIC	Serviceable	62.81 FS	*- FS
5	1		*FUHRUNGSPROFIL LHR SIDE BRACKET	Serviceable	42.20 FS	*- FS
6	1		*FRT BUMPER COATING	Necessary	100.00 FS	*100.00 FS
					Total Parts (\$\$)	1,946.02
						100.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING	New	2,400.00	800.00
Gross Labour Cost (\$\$)			5,680.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >