

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2106278

3 ANSON ROAD #16-00 INV Date 08/09/2021

SPRINGLEAF TOWER
SINGAPORE 079909
Reference CC3/CTI21003005/Kes3q2

Code CTI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 604S

Insured Veh. XD 4251K

Claim No. SNM21D201391/C02

Policy No. DMCVSNW00014672101

Accident Date 03/03/2021

Inspection Date 04/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts Er	Automo	bile	
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CC3/CTI21003005/Kes3q2	
	3 ANSON ROAD # SPRINGLEAF TO	16-00 VERSINGAPORE 079909		Date:	08/09/2021	
				Code:	CTI	
1.		Policy Particulars	- THIRD PARTY	CLAIN	1	
	Insured Veh.	XD 4251K	Veh. Inspected		SHD 604S	
	Policy No.	DMCVSNW00014672101	Coverage (\$)		0.00	
	Claim No.	SNM21D201391/C02	Excess (\$)		0.00	
	Assign From		Assign Date		04/03/2021	
2.		Vehicle Partic	ulars & Conditi	on		
	Make & Model	RENAULT LATITUDE (A)	c.c		1995	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	VF1ABL15AUC283459	Colour		METALLIC WHITE / RED	
	Odometer	283754 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	FALKEN		7 mm	
	L/H Front Tyre	215/60 R16	FALKEN		7 mm	
	R/H Rear Tyre	215/60 R16	SAILUN		6 mm	
	L/H Rear Tyre	215/60 R16	SAILUN		6 mm	
4.		Description	on of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	REAR PORTION			
	DAMAGES SEE DETAILS.					
5.		General	Information			
	Accident Date	03/03/2021	Inspection Dat	е	04/03/2021	
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.			emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	_	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		3 Work	ing Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 604S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER REAR RH	TO REPAIR SEE LABOUR	241.60	-
1	DOOR HINGE LOWER REAR RH	TO REPAIR SEE LABOUR	169.90	-
1	DOOR REGULATOR REAR RH	SERVICEABLE	450.60	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	758.10	-
1	DOOR HANDLE OUTER REAR RH	DENTED	42.10	42.10
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.40	-
1	BUMPER COVER REAR	SERVICEABLE	561.70	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	1,933.20	-
	LESS 10% DISCOUNT		-713.53	-288.68
			6,421.73	2,598.08
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	65.00	-
1	SET FENDER SCREW (SN)	NOT NECESSARY	60.00	-
1	TYRE (SN)	SERVICEABLE	300.00	-
1	RIM (SN)	SERVICEABLE	350.00	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	200.00	-
1	WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	130.00	-
			1,255.00	-
	<u>LABOUR</u>			
	TOWING FEES.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		300.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR .	NOT NECESSARY	300.00	-

Report Ref No. CC3/CTI21003005/Kes3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,900.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	60.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER REAR RH,DOOR HINGE LOWER REAR RH AND FENDER PANEL REAR LH .		1,400.00	400.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		240.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,400.00	440.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	170.00	-
	TO CHECK ELECTICAL LIGHTING CONCERNED.		170.00	20.00
			4,750.00	1,010.00
	GRAND TOTAL		12,426.73	3,608.08

Report Ref No. CC3/CTI21003005/Kes3q2

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 604S

#### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

