

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003007/KPS3Q2
Date: 11/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100415549
Claimant Vehicle No :	GBF6326R	Insured Vehicle No :	SKT3878D
Date of Loss:	26/02/2021	Nature of Claim:	TP
		Claim No:	5574528052SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF6326R	Engine No:	263A50007771536
Make & Model:	OPEL COMBO L2H1, 1.6 D CDTI (A)	Chassis No:	W0L6WYL11H9608169
Reg. Date:	11/01/2017 (Man. Year: 2016)	Odometer:	52751 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	ARGONITE 9 mm	Rear Left Side:	ARGONITE 9 mm
Front Right Side:	ARGONITE 9 mm	Rear Right Side:	ARGONITE 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	711.00	711.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	180.00	110.00	70.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	891.00	821.00	70.00	7.86
+ GST 7.00/7.00% (S\$)	62.37	57.47	4.90	7.86

Nett Amount (S\$)	953.37	878.47	74.90	7.86
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,000.47		
Global Sum Settlement (S\$)		1,000.00		

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 10/03/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE MIRROR ASSY	Cracked	790.00 FL	*790.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	790.00
					- List Item Discount on L Items 10.00/10.00% (\$)	79.00
					Total Parts (\$)	711.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY LH SIDE MIRROR COVER	New	80.00	50.00
2	TO REMOVE LH SIDE DOOR INNER TRIM BOARD FOR REMOVE & RENEW SIDE MIRROR	New	100.00	60.00
Gross Labour Cost (\$\$)			180.00	110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >