

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21003011/UBS3Q2

Date: 14/04/2021

REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D21MFL0000447 |
| Claimant Vehicle No : | SKR3525H | Insured Vehicle No : | SLS5215Y |
| Date of Loss: | 05/03/2021 | Nature of Claim: | TP |
| | | Claim No: | MFL2021D0000975 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SKR3525H | Engine No: | 1NZX791318 |
| Make & Model: | TOYOTA VIOS, 1.5 E (A) | Chassis No: | MR053HY9305077459 |
| Reg. Date: | 17/09/2008 (Man. Year: 2008) | Odometer: | 227284 km |
| Colour: | Black | | |
| Engine Capacity: | 1497 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/55 R15 | Rear Tyre Size: | 195/55 R15 |
| Front Left Side: | Falken 6 mm | Rear Left Side: | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 8,105.50 | 3,805.84 | 4,299.66 | 53.05 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,200.00 | 2,530.00 | 1,670.00 | 39.76 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,305.50 | 6,335.84 | 5,969.66 | 48.51 |
| Approved Total (Overridden) (S\$) | | 5,000.00 | | |
| Nett Amount (S\$) | 12,305.50 | 5,000.00 | 7,305.50 | 59.37 |
| + Car Rental (5.0 x S\$80.00/day) (S\$) | | 400.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 5,407.45 | | |
| Global Sum Settlement (S\$) | | 5,350.00 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 08/03/2021 | |
| Date Inspected: | 08/03/2021 Inspected At: | Profi Automotive (KB) 10 KAKI BUKIT ROAD 2, #01-05 FIRST EAST CENTRE Singapore 417868 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 06 Apr 2021) |
| Parts: | 143 | TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKR3525H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-------------------|------------|------------|
| 1 | 1 | | *FRONT BUMPER | Dented / Deformed | 646.00 FL | *468.20 FL |
| 2 | 1 | | *FRONT BUMPER INNER TOP BRACKET | Twisted | 92.00 FL | *92.00 FL |
| 3 | 2 | | *FRONT BUMPER SIDE RETAINER | Not Necessary | 119.00 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER REINFORCEMENT | Dented | 451.00 FL | *330.45 FL |
| 5 | 1 | | *FRONT BUMPER LOWER MESH | Not Necessary | 86.00 FL | *- FL |
| 6 | 1 | | *FRONT GRILLE | Cracked | 408.00 FL | *325.10 FL |
| 7 | 1 | | *FRONT GRILLE EMBLEM | Necessary | 59.00 FL | *48.50 FL |
| 8 | 1 | | *FRONT HEADLAMP LH | Not Necessary | 593.00 FL | *- FL |
| 9 | 1 | | *FRONT HEADLAMP RH | Not Necessary | 593.00 FL | *- FL |
| 10 | 1 | | *BONNET | Not Necessary | 673.00 FL | *- FL |
| 11 | 1 | | *REAR BUMPER | Distorted | 630.00 FL | *459.75 FL |
| 12 | 2 | | *REAR BUMPER SIDE BRACKET | Not Necessary | 90.00 FL | *- FL |
| 13 | 2 | | *REAR BUMPER SIDE RETAINER | Bent | 19.00 FL | *19.00 FL |
| 14 | 1 | | *REAR BUMPER REFLECTOR LH | Cracked | 84.00 FL | *84.00 FL |
| 15 | 1 | | *REAR BUMPER REFLECTOR RH | Not Necessary | 84.00 FL | *- FL |
| 16 | 1 | | *REAR TAILLAMP PANEL | Repair | 256.00 FL | *- FL |
| 17 | 1 | | *REAR FENDER INNER TRIM | Deformed / Torn | 406.00 FL | *286.50 FL |
| 18 | 1 | | *REAR TAILLAMP LH | Cracked | 475.00 FL | *425.10 FL |
| 19 | 1 | | *REAR TAILLAMP RH | Not Necessary | 475.00 FL | *- FL |
| 20 | 1 | | *BOOTLID | Repair | 611.00 FL | *- FL |
| 21 | 1 | | *BOOTLID WEATHERSTRIP | Twisted | 176.00 FL | *162.84 FL |
| 22 | 1 | | *BOOTLID EMBLEM LOGO | Necessary | 58.00 FL | *48.10 FL |
| 23 | 1 | | *BOOTLID EMBLEM -VIOS | Necessary | 55.00 FL | *46.50 FL |
| 24 | 1 | | *BOOTLID LOCK | Not Necessary | 97.00 FL | *- FL |
| 25 | 1 | | *BOOTLID LOCK STRIKER | Not Necessary | 55.00 FL | *- FL |
| 26 | 1 | | *BOOTLID INNER SPONGE | Not Necessary | 257.00 FL | *- FL |
| 27 | 1 | | *BOOTLID SIDE SPONGE LH | Cracked | 127.00 FL | *127.00 FL |
| 28 | 1 | | *BOOTLID SIDE SPONGE RH | Not Necessary | 127.00 FL | *- FL |
| 29 | 1 | | *SPARE TYRE TOP BOARD | Torn | 115.00 FL | *115.00 FL |
| 30 | 1 | | *SET REAR BUMPER CLIP | Necessary | 40.00 FS | *40.00 FS |
| 31 | 1 | | *SET REAR FENDER INNER TRIM CLIP | Not Necessary | 30.00 FS | *- FS |
| 32 | 1 | | *SET REAR REVERSE SENSOR | Cracked | 400.00 FS | *200.00 FS |
| 33 | 1 | | *JOINT SEALANT | Necessary | 120.00 FS | *50.00 FS |
| 34 | 1 | | *REAR BUMPER LOWER GARNISH | Distorted | 800.00 FS | *680.00 FS |
| 35 | 1 | | *SET FRONT NUMBER PLATE WITH HOLDER | Cracked | 60.00 FS | *40.00 FS |
| 36 | 1 | | *END PANEL | Badly Dented | 675.00 FL | *600.10 FL |
| 37 | 1 | | *END PANEL TOP GARNISH | Cracked | 282.00 FL | *89.65 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 10,324.00 | 4,737.79 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 2,218.50 | 931.95 |
| Total Parts (\$\$) | 8,105.50 | 3,805.84 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | CHECK REAR WIRING AND LIGHTING SYSTEM | New | 80.00 | 20.00 |
| 2 | REMOVE AND RENEW REAR REVERSE SENSOR | New | 120.00 | 50.00 |
| 3 | REMOVE,REFIT REAR LINING ,TRIM AND GARNISH | New | 250.00 | 80.00 |
| 4 | REMOVE AND STRAIGHTEN REAR EXHAUST | New | 300.00 | 0.00 |
| 5 | TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW | New | 200.00 | 0.00 |
| 6 | PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS | New | 1,500.00 | 900.00 |
| 7 | SPRAY PAINTING ON AFFECTED AREAS | New | 1,600.00 | 1,400.00 |
| 8 | APPLY ANTI RUST ON AFFECTED AREAS | New | 150.00 | 80.00 |
| Gross Labour Cost (\$\$) | | | 4,200.00 | 2,530.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >