## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20003010/QVF3E2-1

**Date:** 11/03/2021

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28923076QMY

Claimant Vehicle FBN9418Y Insured Vehicle No : SLM2208U

No:

Date of Loss: 14/02/2020 Nature of Claim: TP Claim No: 620396

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBN9418Y

Make & Model: YAMAHA YZF-R155, 155cc Engine No: G3J6E0176091

Reg. Date: 04/01/2019 (Man. Year: 2018) Chassis No: MH3RG4710KK093765

Colour: Pink/Blue Odometer: 7717 km

Engine Capacity: 155 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17 Rear Tyre Size: 140/70-17 Front Left Side: IRC 7 mm Rear Left Side: IRC 7 mm Rear Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,492.60	3,403.70	2,088.90	38.03
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,130.00	400.00	730.00	64.60
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,622.60	3,803.70	2,818.90	42.56
	Approved Total (Overridden) (S\$)		3,050.00		
	Nett Amount (S\$)	6,622.60	3,050.00	3,572.60	53.95

**INSPECTION** 

Date of Assignment: 25/02/2020

Date Inspected: 24/02/2020 Inspected At: BLK 6 DEFU LANE 10 DEFU IND PARK C

Repairer : AH HWA MOTOR SERVICING

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 11 Mar 2021)

Parts: N/A YAMAHA YZF-R155 155cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBN9418Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT HEADLAMP	Crumpled	580.00 FL	*380.00 FL
2	1	*LAMP STAY	Bent	80.00 FL	*80.00 FL
3	1	*COWL HEAD	Cut	168.00 FL	*168.00 FL
4	1	*LEFT HANDLEBAR	Serviceable	55.00 FL	*- FL
5	1	*RIGHT HANDLEBAR	Bent	55.00 FL	*55.00 FL
6	1	*FORK CLAMP	Bent	185.00 FL	*185.00 FL
7	2	*FORK SET, LEFT / RIGHT	Bent	1,300.00 FL	*800.00 FL
8	1	*FRONT RIM	Bent	360.00 FL	*360.00 FL
9	1	*RIM SHAFT	Bent	20.00 FL	*20.00 FL
10	1	*FRONT BRAKE MASTER PUMP	Serviceable	250.00 FL	*-FL
11	1	*BRAKE LEVER	Bent	28.00 FL	*28.00 FL
12	1	*CLUTCH LEVER	Serviceable	25.00 FL	*- FL
13	1	*FRONT DISC ROTOR	Serviceable	85.00 FL	*- FL
14	1	*RADIATOR	Crumpled	380.00 FL	*295.00 FL
15	1	*SET SIDE MIRROR	Scratched	96.00 FL	*96.00 FL
16	1	*SIDE EXHAUST SIDE GUARD	Scratched	136.00 FL	*136.00 FL
17	1	*REAR EXHAUST END CAP	Scratched	35.00 FL	*35.00 FL
18	1	*RIGHT SIDE FOOTREST	Bent	28.00 FL	*28.00 FL
19	1	*RIGHT SIDE FOOTREST BRACKET	Bent	68.00 FL	*68.00 FL
20	1	*BRAKE PEDAL	Bent	38.00 FL	*38.00 FL
21	1	*PILLION SEAT	Crumpled	78.00 FL	*78.00 FL
22	1	*FUEL TANK TOP COVER	Scratched	48.00 FL	*48.00 FL
23	1	*RIGHT SIDE FAIRING	Crumpled	68.00 FL	*68.00 FL
24	1	*LEFT SIDE FAIRING	Crumpled	68.00 FL	*68.00 FL
25	1	*RIGHT SIDE LOWER FAIRING	Crumpled	48.00 FL	*48.00 FL
26	1	*LEFT SIDE LOWER FAIRING	Serviceable	48.00 FL	*- FL
27	1	*LEFT SIDE REAR FAIRING	Crumpled	55.00 FL	*55.00 FL
28	1	*RIGHT SIDE REAR FAIRING	Serviceable	55.00 FL	*- FL
29	1	*LEFT SIDE TAIL TOP COVER	Serviceable	28.00 FL	*- FL
30	1	*FRONT FENDER	Crumpled	65.00 FL	*65.00 FL
31	1	*STEERING STEM	Bent	195.00 FL	*195.00 FL
32	1	*SET STEERING CONE BEARING	Necessary	150.00 FL	*80.00 FL
33	1	*HANDLEBAR BALANCER	Crumpled	16.00 FL	*16.00 FL
34	1	*RIM BEARING	Jammed	60.00 FS	*40.00 FS
35	1	*SET FULL BODY DECAL	Necessary	950.00 FS	*200.00 FS
36	1	*BATTERY	Serviceable	58.00 FS	*- FS
37	1	*RADIATOR COOLANT	Necessary	20.00 FS	*20.00 FS
F=Fra	nchise part. S=SpcN	ett. L=ListItemDisc.	Cult T-4-1 (OA)	F 000 00	2.752.00
		List Itam Dissecut on L	Sub Total (S\$)	<b>5,982.00</b>	<b>3,753.00</b>
		- List Item Discount on L	. items 10.00/10.00% (5\$) 	489.40	349.30
			Total Parts (S\$)	5,492.60	3,403.70

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING (2 WAYS)	New	70.00	70.00
2	BODY FRAME PRESSING AND ALIGNMENT - CHASSIS FRAME BEHIND HEAD POST BENT	New	480.00	150.00
3	WORKMANSHIP	New	580.00	180.00
	Gross Labour Cost (S\$)		1,130.00	400.00
	Report was unsubmitted during t	his print-out.		

< END OF ESTIMATES >