



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105348

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 01/08/2021
Reference CC6/CTI21003022/Ars3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBH 8937D
Insured Veh. SLP 5846S
Claim No. SNM20D201268
Policy No. DMPCSNW00053962002
Accident Date 21/02/2021
Inspection Date 10/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21003022/Ars3q2	
			Date: 01/08/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 5846S	Veh. Inspected	GBH 8937D	
Policy No.	DMPCSNW00053962002	Coverage (\$)	0.00	
Claim No.	SNM20D201268	Excess (\$)	0.00	
Assign From		Assign Date	10/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFHT02P300245824	Colour	SILVER	
Odometer	107232 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MAXMILER	6 mm	
L/H Front Tyre	195 R15C	MAXMILER	6 mm	
R/H Rear Tyre	195 R15C	MAXMILER	6 mm	
L/H Rear Tyre	195 R15C	MAXMILER	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/02/2021	Inspection Date	10/03/2021	
Survey held at	RYDER AUTO WORKSHOP LLP 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 8937D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	540.00	540.00
1	REAR BUMPER BRACKET (MIDDLE)	NOT NECESSARY	160.00	-
1	REAR BUMPER O/S & N/S RETAINER	NECESSARY	132.00	132.00
1	REAR TAIL-GATE	DENTED	1,789.20	1,789.20
1	REAR TAIL-GATE WEATHERSTRIP	NOT NECESSARY	140.00	-
1	REAR TAIL-GATE 'TOYOTA' EMBLEM	NECESSARY	67.60	67.60
1	REAR TAIL-GATE 'TOYOTA HIACE' EMBLEM	NECESSARY	68.50	68.50
1	REAR TAIL-GATE LOCK	NOT NECESSARY	280.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	578.50	-
	LESS 25% DISCOUNT		-938.95	-649.33
			2,816.85	1,947.97
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAIL-GATE '70' KMPH STICKER (SN)	NECESSARY	15.00	15.00
1	REAR TAIL-GATE '8' PAX STICKER (SN)	NECESSARY	15.00	15.00
1	REAR TAIL-GATE COMPANY STICKER (SN)	NECESSARY	400.00	280.00
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	120.00	120.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			910.00	690.00
	<u>LABOUR</u>			
	TO DISMANTLE REAR PORTION ,STRAIGHTEN AND WELDING .INCLUSIVE OF THE REPAIR OF REAR END PANEL .INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	400.00
	TO SPRAY PAINTING .		800.00	500.00
	TO REMOVE AND REFIT REAR TAIL GATE .(FITTINGS)		150.00	80.00
	TO REMOVE AND REFIT REAR WINDSCREEN .		160.00	120.00
	TO RE-SEAL ANTI-RUST.	NOT NECESSARY	50.00	-
			1,960.00	1,100.00
	GRAND TOTAL		5,686.85	3,737.97

Report Ref No. CC6/CTI21003022/Ars3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00
---	--	--	----------

Report Ref No. CC6/CTI21003022/Ars3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 8937D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 8937D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

