

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21003025/R1BS3Q2
Date: 07/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	EF2211D	Insured Vehicle No :	SLT4965S
Date of Loss:	04/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000991

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EF2211D	Engine No:	27491030584371
Make & Model:	MERCEDES-BENZ C180, 1.6 EXCLUSIVE R17 LED (A)	Chassis No:	WDD2050402R160118
Reg. Date:	03/05/2016 (Man. Year: 2016)	Odometer:	36424 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	771.24	582.12	189.12	24.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	4,370.00	930.00	17.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,071.24	4,952.12	1,119.12	18.43
+ GST 7.00/7.00% (S\$)	424.99	346.65	78.34	18.43

Nett Amount (S\$)	6,496.23	5,298.77	1,197.46	18.43
+ Car Rental (7.0 x S\$107.00/day) (S\$)		749.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,055.22		

INSPECTION

Date of Assignment:	08/03/2021		
Date Inspected:	11/03/2021	Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 May 2021)

Parts: 143 MERCEDES-BENZ C180 1.6 EXCLUSIVE R17 LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for EF2211D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH/R DISC WHEEL	Scratched	582.12 FS	*582.12 FS
2	1		*LEFT WING MIRROR SIGNAL LAMP	Repair	189.12 FS	*- FS
Total Parts (\$\$)					771.24	582.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	SUPPLY & TRANFER 1PC REAR LEFT RIM	New	60.00	60.00
3	INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
4	REMOVE ,REPAIR & INSTALL SUPPORT ASSY FROM VEHICLE FRAME	New	1,920.00	1,440.00
5	RESRPAY REAR LEFT DOOR ,REAR LEFT FENDER ,REAR BUMPER & LEFT WING MIRROR HOUSING	New	2,400.00	1,950.00
			Gross Labour Cost (S\$)	5,300.00
				4,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >