

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003027/ABS3Q2
Date: 11/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993670
Claimant Vehicle No :	SKW9647Z	Insured Vehicle No :	SMD3827L
Date of Loss:	08/03/2021	Nature of Claim:	TP
		Claim No:	5439612118SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW9647Z	Engine No:	L15B4026166
Make & Model:	HONDA VEZEL, 1.5 X A (A)	Chassis No:	RU11106140
Reg. Date:	23/11/2015 (Man. Year: 2015)	Odometer:	73954 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,983.64	12,961.56	6,022.08	31.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	3,110.00	620.00	16.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,713.64	16,071.56	6,642.08	29.24
Approved Total (Overridden) (S\$)		12,800.00		

(S\$)	22,713.64	12,800.00	9,913.64	43.65
+ GST 7.00/7.00% (S\$)	1,589.95	896.00	693.95	43.65
Nett Amount (S\$)	24,303.59	13,696.00	10,607.59	43.65
+ Loss of Use (18.0 x S\$80.00/day) (S\$)		1,440.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		15,172.45		
Global Sum Settlement (S\$)		15,100.00		

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 08/03/2021

Inspected At:

 RYDER AUTO PTE LTD
 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB
 SINGAPORE 417921

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	840.00 FL	*840.00 FL
2	1		*REAR BUMPER O/S & N/S TOP GARNISH	O/S Deformed	586.40 FL	*195.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
4	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
5	1		*REAR BUMPER O/S & N/S REFLECTOR	O/S Cracked	208.00 FL	*104.00 FL
6	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	125.00 FL	*65.00 FL
7	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
8	1		*REAR END PANEL	Distorted	611.90 FL	*611.90 FL
9	1		*REAR END PANEL INNER TRIM	Deformed	150.00 FL	*150.00 FL
10	2		*REAR O/S & N/S TAIL-LAMP	Cracked	940.00 FL	*940.00 FL
11	2		*REAR O/S & N/S TAIL-LAMP CLIPS	Necessary	20.00 FS	*20.00 FS
12	1		*REAR TAIL GATE	Distorted	1,378.00 FL	*1,100.00 FL
13	1		*REAR TAIL GATE WEATHERSTRIP	Cut	265.00 FL	*265.00 FL
14	1		*REAR TAIL GATE HONDA EMBLEM	Not Necessary	95.00 FL	*- FL
15	1		*REAR TAIL GATE VEZEL EMBLEM	Necessary	85.00 FL	*55.00 FL
16	1		*REAR TAIL GATE INNER TRIM	Deformed	310.00 FL	*285.00 FL
17	1		*REAR TAIL GATE INNER TRIM CLIPS (11 PCS)	Necessary	34.00 FS	*34.00 FS
18	1		*REAR TAIL GATE HANDLE	Not Necessary	80.00 FL	*- FL
19	1		*REAR TAIL GATE LOCK (UPPER)	Damaged	350.00 FL	*182.00 FL
20	1		*REAR TAIL GATE LOCK (LOWER)	Not Necessary	130.00 FL	*- FL
21	2		*REAR TAIL GATE O/S & N/S REFLECTOR	Cracked	940.00 FL	*729.00 FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	90.00 FS	*90.00 FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
24	2		*REAR BOOT FLOOR O/S & N/S CORNER PANEL	Repair	465.80 FL	*- FL
25	1		*REAR SPARE WHEEL TANK	Buckled	1,318.75 FL	*1,230.00 FL
26	1		*REAR SPARE WHEEL BOARD COVER	Deformed	561.10 FL	*305.00 FL
27	1		*REAR SPARE WHEEL TANK INSULATOR	Not Necessary	374.40 FL	*- FL
28	1		*REAR SPARE WHEEL TANK TOOL BOX	Deformed	245.60 FL	*245.60 FL
29	2		*REAR O/S & N/S FENDER INNER TRIM	Deformed	845.60 FL	*622.00 FL
30	2		*REAR O/S & N/S FENDER INNER TRIM HOOK GARNISH	Not Necessary	200.00 FL	*- FL
31	1		*REAR SPARE WHEEL TANK UNDER COVER	Deformed	310.60 FL	*310.60 FL
32	1		*REAR EXHAUST MUFFLER	Not Necessary	991.60 FL	*- FL
33	2		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	223.00 FL	*- FL
34	1		*REAR BUZZER	Cracked	310.00 FL	*68.00 FL
35	1		*FRONT BUMPER	Deformed	1,042.20 FL	*821.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT BUMPER ENFORCEMENT	Bent	490.00 FL	*321.00 FL
37	10		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
38	2		*FRONT BUMPER O/S & N/S RETAINER	Necessary	306.80 FL	*64.00 FL
39	2		*FRONT BUMPER BRACKET	Not Necessary	130.00 FL	*- FL
40	1		*FRONT BUMPER ENFORCEMENT BRACKET (UPPER)	Cracked	106.80 FL	*68.00 FL
41	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	215.50 FL	*215.50 FL
42	1		*FRONT GRILLE	Cracked	442.00 FL	*385.00 FL
43	1		*FRONT GRILLE OUTER	Cut	580.60 FL	*580.60 FL
44	1		*FRONT GRILLE EMBLEM	Necessary	80.00 FL	*48.00 FL
45	4		*FRONT GRILLE CLIPS	Necessary	16.00 FS	*16.00 FS
46	1		*FRONT BONNET	Dented	1,159.90 FL	*892.00 FL
47	2		*FRONT BONNET O/S & N/S HINGES	Not Necessary	226.10 FL	*- FL
48	1		*FRONT BONNET LOCK (LOWER)	Not Necessary	220.00 FL	*- FL
49	1		*FRONT O/S & N/S HEAD-LAMP	Cracked	4,816.40 FL	*3,700.00 FL
50	2		*FRONT O/S & N/S HEAD-LAMP RETAINER	Cracked	130.00 FL	*130.00 FL
51	1		*FRONT REGN NO.PLATE	Bent	45.00 FS	*30.00 FS
52	1		*FRONT REGN NO.PLATE BRACKET	Deformed	29.00 FS	*29.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,561.05	16,067.20
- List Item Discount on L Items 20.00/20.00% (\$)	4,577.41	3,105.64
Total Parts (\$)	18,983.64	12,961.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,600.00	1,500.00
2	TO SPRAY PAINTING	New	1,400.00	1,200.00
3	TO REMOVE & REPLACE REAR EXHAUST	New	100.00	0.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
5	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	50.00	50.00
6	TO REMOVE & REPLACE REAR TAIL-GATE (MECHANISM)	New	80.00	80.00
7	TO RE-SET ELECTRICAL SYSTEM	New	180.00	0.00
8	TO CHECK WIRING	New	100.00	60.00
9	TO RE-SEAL ANTI-RUST	New	100.00	100.00
Gross Labour Cost (\$\$)			3,730.00	3,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >