

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD TOYOTA WISH (SKA5661Z)
Date of Loss	5 March 2021
Time of Loss	15:29
Loss Description	SMU1937B (INSD) C/W REAR OF SKA5661Z (TP)
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	-\$41,891.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SKA5661Z

Registration State

SINGAPORE

Mileage

271179

Purchase Date

DD/MM/YYYY



Registration Date *

14/03/2011



Age of Vehicle

9

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2011

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION





Driver Name

SIM CHOW WAN

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD TOYOTA	<input type="text" value="TOYOTA"/>
Model	WISH	<input type="text" value="WISH 1.8 CVT"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JTDGG20W505001707"/>
Engine No		<input type="text" value="2ZR0782302"/>
Engine Capacity		<input type="text" value="1798"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	16 August 1949	<input type="text" value="DD/MM/YYYY"/> 
Age	71	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Unknown	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	S0155281C	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

195/65R15

Front left side

WESTLAKE3mm

Front right side

WESTLAKE3mm

Spare wheel

Rear Tyre Size

195/65R15

Rear left side

WESTLAKE3mm

Rear right side

WESTLAKE3mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

25

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition








Taxes & Ratio












Parts & Labour












Miscellaneous











Summary


Parts

Add		Approve		Deny	Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR WINDSCREEN GLASS MOULDING	Necessary	0	112	No	0	25	0	0	84
	0	1		TAILGATE WINDSCREEN GLASS	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE	Bent	0	1123.2	No	0	25	0	0	842.4
	0	1		TAILGATE LOGO	Necessary	0	68.5	No	0	25	0	0	51.38
	0	1		TAILGATE LOGO - VALVE MATIC	Necessary	0	68.5	No	0	25	0	0	51.38
	0	1		TAILGATE OUTER CHROME MOULDING	Damaged	0	290	No	0	25	0	0	217.5
	0	1		TAILGATE INNER LOCK	Dented	0	398	No	0	25	0	0	298.5

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILGATE INNER CATCH	Repair	0	0	No	0	0	0	0	0
	0	1		TAILGATE INNER TRIM BOARD	Cracked	0	450	No	0	25	0	0	337.5
	0	1		TAILGATE INNER HANDLE	Dented	0	32	No	0	25	0	0	24
	0	1		TAILGATE DAMPER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE DAMPER RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE INNER HANDLE	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE INNER CENTRE GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE INNER GARNISH LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE INNER GARNISH RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR TOOL BOX	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR NUMBER PLATE LAMP LH	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR NUMBER PLATE LAMP RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR WIPER MOTOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILLAMP LED RH	Cracked	0	675	No	0	25	0	0	506.25
	0	1		TAILLAMP LED LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE LAMP LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE LAMP RH	Cut	0	596	No	0	25	0	0	447
	0	1		REAR BUMPER	Bent	0	566	No	0	25	0	0	424.5
	0	1		REAR BUMPER REFLECTOR LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER REFLECTOR RH	Cracked	0	68.5	No	0	25	0	0	51.38
	0	1		REAR BUMPER BRACKET LH	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER BRACKET RH	Dented	0	55.6	No	0	25	0	0	41.7

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER SIDE RETAINER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER SIDE RETAINER RH	Damaged	0	128.6	No	0	25	0	0	96.45
	0	1		REAR END PANEL	Bent	0	519.8	No	0	25	0	0	389.85
	0	1		REAR END PANEL INNER GARNISH	Buckled	0	145	No	0	25	0	0	108.75
	0	1		REAR END PANEL INNER CROSSMEMBER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER TRIM BOARD LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER TRIM BOARD RH	Cracked	0	692.42	No	0	25	0	0	519.32
	0	1		REAR FENDER INNER SHIELD LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER SHIELD RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR TOOLS BOARD COVER	Dented	0	180	No	0	25	0	0	135

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR EXHAUST SILENCER	Bent	0	685	No	0	25	0	0	513.75
	0	2		REAR EXHAUST MOUNTING	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST HEAT SHIELD	Repair	0	0	No	0	0	0	0	0
	0	1		CENTRE EXHAUST PIPE	Bent	0	1150	No	0	25	0	0	862.5
	0	1		REAR SPARETYRE CARRIER	Bent	0	329	No	0	25	0	0	246.75
	0	1		KEYLESS SENSOR	Cracked	0	189.5	No	0	25	0	0	142.13
	0	1		AIR VENT RH	Dented	0	71	No	0	25	0	0	53.25
	0	1		FENDER RH	Repair	0	0	No	0	0	0	0	0





Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	0	1000	0	0	Reviewing		
	0		SPRAY PAINTING ON ACCIDENT AREA	0	800	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		CHECK & REPAIR WIRING SYSTEM	0	20	0	0	Reviewing		
	0		R&R INNER TRIM, INNER GARNISH TO ASSIST REPAIR	0	100	0	0	Reviewing		
	0		R&R AND RESET REAR BUMPER SENSOR & CAMERA	0	60	0	0	Reviewing		
	0		R&R REAR WINDSCREEN GLASS	0	120	0	0	Reviewing		
	0		R&R AND RE-ADJUST REAR EXHAUST SYSTEM	0	80	0	0	Reviewing		
	0		RESPRAY TUFF KOTE ON ACCIDENT AREAS	0	60	0	0	Reviewing		
	0		R&R TAILGATE COMPONENTS	0	60	0	0	Reviewing		
	0		R&R REAR SEAT, CARPET TO ASSIST REPAIR	0	0	0	0	Deny		
	0		REAR 1/4 GLASS SEALANT	0	0	0	0	Deny		
	0		REAR 1/4 GLASS INNER SEAL	0	0	0	0	Deny		
	0		REAR 1/4 GLASS CLEANER AND PRIMER	0	0	0	0	Deny		



Assessment Details

General & Workshop Details

Vehicle & Driver Details





Vehicle Condition











Taxes & Ratio













Parts & Labour





Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 8 DAYS	Reviewing	0	0		
	0	TAILGATE RUBBER (\$320.00) (50%)	Reviewing	0	160	DISTORTED / DENTED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR WINDSCREEN GLASS SEALANT	Reviewing	0	40	NECESSARY	
	0	REAR WINDSCREEN GLASS INNER SEAL	Reviewing	0	30	NECESSARY	
	0	REAR WINDSCREEN PRIMER AND CLEANER	Reviewing	0	20	NECESSARY	
	0	REAR NUMBER PLATE	Reviewing	0	45	BENT	
	0	REAR END PANEL SEALANT	Reviewing	0	30	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	1 SET REAR END PANEL INNER GARNISH CLIPS	Reviewing	0	50	NECESSARY	
	0	REAR BUMPER CLIPS	Reviewing	0	50	NECESSARY	
	0	REAR SPARETYRE INSULATOR PAD	Deny	0	0	SERVICEABLE	
	0	REAR REVERSE SENSOR	Reviewing	0	200	DENTED	
	0	SOLAR FILM	Deny	0	0	NOT NECESSARY	
	0	REVERSE CAMERA	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	TAILGATE TOP SPOILER SEALANT	Deny	0	0	NOT NECESSARY	
	0	TAILGATE TRIM BOARD CLIPS	Reviewing	0	50	NECESSARY	

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$9,420.24
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$6,445.24
Labour	\$0.00	\$2,300.00
Miscellaneous	\$0.00	\$675.00

Submit for Review



Assessment Details

General & Workshop Details

Vehicle & Driver Details



Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	7500		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$7,500.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$7,500.00

Submit for Review