

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21003036/R1VD3E2

Date: 15/04/2021

REFERENCE

Insured/Claimant: KUNA SHEKARAN S/O RAMASAMY Policy No: D20MPC0004809
Date of Loss: 28/02/2021 Nature of Claim: OD Claim No: MPC2021D0000924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW2811Z**
Make & Model: VOLKSWAGEN GOLF SPORTS, 1.4 TSI (A) Engine No: CDL023194
Reg. Date: 15/03/2010 (Man. Year: 2009) Chassis No: WVVZZZ1KZAW242926
Colour: Blue Odometer: 160069 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$83,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40ZR18 Rear Tyre Size: 235/40ZR18
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,626.80	10,111.52	9,515.28	48.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,620.00	320.00	16.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,566.80	11,731.52	9,835.28	45.60
Approved Total (Overridden) (S\$)		9,400.00		
- Excess (S\$)	750.00	750.00	0.00	0.00
Nett Amount (S\$)	20,816.80	8,650.00	12,166.80	58.45

INSPECTION

Date of Assignment: 08/03/2021
Date Inspected: 08/03/2021 Inspected At: J's Garage Pte Ltd (HQ)
48 Toh Guan Road East, Enterprise Hub #02-108
Singapore 608586
Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2021)
Parts:	144	VOLKSWAGEN GOLF SPORTS 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW2811Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	968.00 F	*968.00 FL
2	1		*FRONT BUMPER UPPER SPOILER	Serviceable	222.00 F	*- FL
3	1		*FRONT BUMPER LOWER SPOILER	Serviceable	671.00 F	*- FL
4	1		*FRONT BUMPER RH RETAINER	Cracked	72.60 F	*72.60 FL
5	1		*FRONT BUMPER LH RETAINER	Cracked	72.60 F	*72.60 FL
6	1		*HEADLAMP LOWER BRACKET LH	Cracked	129.80 F	*129.80 FL
7	1		*HEADLAMP LOWER BRACKET RH	Cracked	129.80 F	*129.80 FL
8	1		*BUMPER LOWER GRILLE	Serviceable	690.00 F	*- FL
9	1		*FRONT GRILLE	Cracked	472.00 F	*472.00 FL
10	1		*LAMP GRILLE LH	Serviceable	175.00 F	*- FL
11	1		*LAMP GRILLE RH	Serviceable	175.00 F	*- FL
12	1		*LAMP GRILLE PLATE LH	Serviceable	45.00 F	*- FL
13	1		*LAMP GRILLE PLATE RH	Serviceable	45.00 F	*- FL
14	1		*HEADLAMP LH	Cracked	1,850.00 F	*1,850.00 FL
15	1		*HEADLAMP RH	Cracked	1,850.00 F	*1,850.00 FL
16	1		*LED DAYLIGHT LH	Serviceable	682.00 F	*- FL
17	1		*LED DAYLIGHT RH	Serviceable	682.00 F	*- FL
18	1		*BONNET	Bent	858.00 F	*858.00 FL
19	1		*BONNET UNDERTRAY HEATSHIELD	Serviceable	120.00 F	*- FL
20	1		*BONNET HINGE LH	Serviceable	80.00 F	*- FL
21	1		*BONNET HINGE RH	Serviceable	80.00 F	*- FL
22	1		*SUPPORT CARRIER	Cracked	1,100.00 F	*1,100.00 FL
23	1		*AIR DUCT 1	Serviceable	50.00 F	*- FL
24	1		*AIR DUCT 2	Serviceable	20.00 F	*- FL
25	1		*AIR DUCT 3	Serviceable	22.00 F	*- FL
26	1		*HEADLAMP UPPER BRACKET LH	Bent	75.00 F	*75.00 FL
27	1		*HEADLAMP UPPER BRACKET RH	Bent	75.00 F	*75.00 FL
28	1		*LOWER REINFORCEMENT	Serviceable	240.00 F	*- FL
29	1		*REINFORCEMENT	Serviceable	600.00 F	*- FL
30	1		*RADIATOR	Bent	550.00 F	*550.00 FL
31	1		*COOLER	Serviceable	750.00 F	*- FL
32	1		*COOLER PIPE 1	Serviceable	350.00 F	*- FL
33	1		*COOLER HOSE 1	Serviceable	160.00 F	*- FL
34	1		*COOLER PIPE 2	Serviceable	220.00 F	*- FL
35	1		*COOLER HOSE 2	Serviceable	240.00 F	*- FL
36	1		*COOLER HOSE 3	Serviceable	75.00 F	*- FL
37	1		*COOLER HOSE 4	Serviceable	550.00 F	*- FL
38	1		*COOLER AIR PIPE	Serviceable	210.00 F	*- FL
39	1		*COOLER VALVE	Serviceable	210.00 F	*- FL
40	1		*CONDENSER	Bent	550.00 F	*550.00 FL
41	1		*FAN COWL	Deformed	210.00 F	*210.00 FL
42	1		*FAN COWL AIR DUCT LH	Serviceable	55.00 F	*- FL
43	1		*FAN COWL AIR DUCT RH	Serviceable	55.00 F	*- FL
44	1		*SMALL ELECTRICAL FAN	Cracked	500.00 F	*500.00 FL
45	1		*BIG ELECTRICAL FAN	Cracked	850.00 F	*850.00 FL
46	1		*FENDER LH	Bent	480.00 F	*480.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FENDER RH	Repair	480.00 F	*- FL
48	1		*BONNET LOCK	Serviceable	210.00 F	*- FL
49	1		*ENGINE LOWER COVER	Serviceable	200.00 F	*- FL
50	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
51	1		*BATTERY TRAY BRACKET	Cracked	120.00 F	*120.00 FL
52	1		*HEADLIGHT NOZZLE	Cracked	85.00 F	*85.00 FL
53	1		*BONNET UPPER LOCK	Bent	95.00 F	*95.00 FL
54	1		*TURBO HOSE	Cut	120.00 F	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,626.80	11,232.80
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	1,121.28
Total Parts (S\$)	19,626.80	10,111.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY FRONT BUMPER,LIP SUPPORT PANEL RH LH,FENDER RH LH	New	1,000.00	800.00
2	TO FOCUS DISTANCE SENSORS	New	60.00	40.00
3	TO CHECK WIRING	New	40.00	40.00
4	TO APPLY RUST PROOFING FRONT PORTION	New	40.00	40.00
5	TO RENEW FRT BUMPER,BONNET,CONDENSER RADIATOR HOSES PIPING ETC.TO REPAIR FRT SUPPORT PANEL,BOTH DOORS AND A-PILLARS	New	800.00	700.00
Gross Labour Cost (\$)			1,940.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >