



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YVONNE ANG			Ref: CS3/ASM20014283/Gtf3e2-1 Date: 13/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SLZ 5155A	Veh. Inspected	SMD 3033K
	Policy No.		Coverage (\$)	0.00
	Claim No.	S0M02Z8V	Excess (\$)	0.00
	Assign From	YVONNE ANG	Assign Date	08/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC250	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WDC2533462F446652	Colour	WHITE
	Odometer	32592 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/50 R19	MICHELIN	6 mm
	L/H Front Tyre	255/50 R19	MICHELIN	6 mm
	R/H Rear Tyre	255/50 R19	MICHELIN	6 mm
	L/H Rear Tyre	255/50 R19	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	17/12/2020	Inspection Date	12/03/2021
	Survey held at	17B Jalan Hock Chye s 538196		
	Repairer	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM)		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	