

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003040/KBA3Q2
Date: 27/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993660
Claimant Vehicle No :	SMC1871B	Insured Vehicle No :	SLE3209C
Date of Loss:	04/03/2021	Nature of Claim:	TP
		Claim No:	8084244034SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC1871B	Engine No:	2NR5235542
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3601131359
Reg. Date:	27/06/2018 (Man. Year: 2018)	Odometer:	89394 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Yokohama 3 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,478.67	1,836.80	641.87	25.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,180.00	520.00	30.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,178.67	3,016.80	1,161.87	27.80
Approved Total (Overridden) (S\$)		2,400.00		

(S\$)	4,178.67	2,400.00	1,778.67	42.57
+ GST 7.00/7.00% (S\$)	292.51	168.00	124.51	42.57
Nett Amount (S\$)	4,471.18	2,568.00	1,903.18	42.57
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,875.45		

INSPECTION

Date of Assignment: 08/03/2021

Date Inspected: 09/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Buckled	554.10 FL	*554.10 FL
2	1		*REAR BUMPER REINFORCEMENT	Buckled	346.80 FL	*346.80 FL
3	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	279.40 FL	*139.70 FL
4	1		*REAR END PANEL	Repair	582.80 FL	*- FL
5	1		*END PANEL TOP GARNISH	Mtg Distorted	232.10 FL	*232.10 FL
6	1		*BOOT LID	Buckled	754.30 FL	*754.30 FL
7	1		*BOOT LID LOGO	Necessary	52.20 FL	*52.20 FL
8	1		*BOOT LID VIOS EMBLEM	Necessary	53.60 FL	*53.60 FL
9	1		*BOOT LID E EMBLEM	Necessary	49.60 FL	*49.60 FL
10	1		*SET REAR BUMPER PARKING SENSOR	Dented	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,204.90	2,382.40
- List Item Discount on L Items 25.00/25.00% (S\$)	726.23	545.60
Total Parts (S\$)	2,478.67	1,836.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY UNDERSEALING	New	80.00	30.00
2	TO REMOVE SPARE TYRE ,REAR SEAT ,TRIM BOARD AND CARPET	New	120.00	50.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00	600.00
4	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	700.00	500.00
Gross Labour Cost (\$\$)			1,700.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >